

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22009325/UVY3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SLM8849E**Insured Vehicle No :** SFN8413U

Date of Loss: 17/09/2022

Nature of Claim: TP

Claim No: 2022 22006852JK

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLM8849E**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGGH647437

Reg. Date: 17/04/2017 (Man. Year: 2017)

Chassis No: KNAFJ411MH5714618

Colour: Blue

Odometer: 194447 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Habilead 6 mm

Rear Left Side:

APLUS 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side:

APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,238.14	1,825.60	2,412.54	56.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	720.00	1,050.00	59.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,008.14	2,545.60	3,462.54	57.63
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,008.14	2,000.00	4,008.14	66.71
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/09/2022

Date Inspected: 11/10/2022 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49 Synergy@KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2022)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8849E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LOGO	Necessary	48.00 FL	*48.00 FL
2	1		*FRONT BUMPER	Deformed / Torn	696.00 FL	*633.00 FL
3	1		*FRONT BUMPER FOG LAMP INNER GARNISH -L	Not Necessary	205.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP OUTER GARNISH -L	Not Necessary	300.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINERS	N/S Bent	121.60 FL	*45.00 FL
6	1		*FRONT HEADLAMP -L	Cracked	1,548.00 FL	*810.00 FL
7	1		*FRONT FENDER	Repair	617.00 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD -L	Torn	166.00 FL	*166.00 FL
9	1		*FRONT INNER GARNISH -L	Not Necessary	105.00 FL	*- FL
10	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	148.00 FL	*- FL
11	1		*FRONT BUMPER BEAM	Bent	322.00 FL	*282.00 FL
12	1		*FRONT BUMPER UNDERCOVER	Not Necessary	288.00 FL	*- FL
13	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FS	*40.00 FS
14	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,694.60	2,024.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	456.46	198.40
Total Parts (\$\$)	4,238.14	1,825.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	120.00	20.00
2	TO APPLY UNDERCOATING	New	150.00	0.00
3	TO RESPRAY PAINTING ON AFFECTED AREAS	New	800.00	300.00
4	PANEL BEATING	New	700.00	400.00
Gross Labour Cost (\$\$)			1,770.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >