

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III22009336/KCY3E2**Date:** 10/03/2023REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D18MFL0003414_03

Date of Loss: 06/09/2022

Nature of Claim: OD

Claim No: MFL2022D0005007

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNF904U**

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A)

Engine No: 2ZR2M92442

Reg. Date: 29/04/2022 (Man. Year: 2021)

Chassis No: ZWR800507790

Colour: Metallic Black

Odometer: 22532 km

Engine Capacity: 1797 cc

Market Value/New Car Price: S\$188,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Davanti 9 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Davanti 9 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,644.77	4,325.85	11,318.92	72.35
Miscellaneous Items	111.00	106.00	5.00	4.50
Labour	1,880.00	1,320.00	560.00	29.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,635.77	5,751.85	11,883.92	67.39
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	17,635.77	4,251.85	13,383.92	75.89
+ GST 7.00/7.00% (S\$)	1,234.50	297.63	936.87	75.89
Nett Amount (S\$)	18,870.27	4,549.48	14,320.79	75.89

INSPECTION

Date of Assignment:	22/09/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	22/09/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Mar 2023)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF904U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	926.30 FL	*- FL
2	1		*FRT BONNET LOCK	Repair	99.80 FL	*- FL
3	1		*FRT BONNET CHROME GARNISH	Serviceable	527.30 FL	*- FL
4	1		*FRT BONNET LH HINGE	Repair	67.20 FL	*- FL
5	1		*FRT BONNET RH HINGE	Repair	67.20 FL	*- FL
6	1		*LH HEADLAMP	Serviceable	3,606.20 FL	*- FL
7	1		*RH HEADLAMP	Mtg Cracked	3,606.20 FL	*3,606.20 FL
8	1		*FRT BUMPER	Buckled	663.90 FL	*663.90 FL
9	1		*FRT BUMPER RH FOG LAMP GARNISH	Serviceable	113.50 FL	*- FL
10	1		*FRT BUMPER LH FOGLAMP GARNISH	Serviceable	112.50 FL	*- FL
11	1		*FRT BUMPER UNDERCOVER	Serviceable	150.60 FL	*- FL
12	1		*FRT GRILLE ASSEMBLY	Serviceable	1,093.60 FL	*- FL
13	1		*FRT LOWER GRILLE	Cracked	1,099.20 FL	*1,099.20 FL
14	1		*FRT GRILLE EMBLEM	Not Necessary	222.00 FL	*- FL
15	1		*FRT REINFORCEMENT SPONGE	Deformed	750.50 FL	*75.50 FL
16	1		*FRT REINFORCEMENT BAR	Bent	323.00 FL	*323.00 FL
17	1		*FRT BRACE PANEL	Repair	99.10 FL	*- FL
18	1		*FRT HYBRID COOLER	Serviceable	986.70 FL	*- FL
19	1		*FRT CONDENSOR	Serviceable	1,421.90 FL	*- FL
20	1		*FRT RADIATOR	Serviceable	2,423.20 FL	*- FL
21	1		*FRT FAN SHROUD	Serviceable	314.90 FL	*- FL
22	1		*FRT SUPPORT PANEL	Repair	1,869.10 FL	*- FL
23	1		*FRT AIR GUIDE LH UPPER	Serviceable	71.40 FL	*- FL
24	1		*FRT AIR GUIDE LH LOWER	Serviceable	86.50 FL	*- FL
25	1		*FRT AIR GUIDE RH UPPER	Serviceable	71.40 FL	*- FL
26	1		*FRT AIR GUIDE RH LOWER	Serviceable	86.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	20,859.70	5,767.80
- List Item Discount on L Items 25.00/25.00% (S\$)	5,214.93	1,441.95
Total Parts (S\$)	15,644.77	4,325.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	FRONT NUMBER PLATE (BENT)	50.00	45.00
3	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			111.00	106.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE FRONT DAMAGE PARTS, CUT, WELD AND REPLACE RECOMMENDED PARTS.	New	800.00	500.00
2	TO PUTTY & SPRAY PAINTING ON FRT BONNET, FRT BUMPER, FRT GRILLE, FRT SUPPORT PANEL.	New	1,000.00	800.00
3	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTING & RESET HEADLAMP FOCUSING	New	80.00	20.00
Gross Labour Cost (S\$)			1,880.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >