

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009338/AQY3Q2**Date:** 30/05/2023**REFERENCE**

Insured/Claimant: Eeong Electrical Engineering Pte Ltd
Date of Loss: 02/09/2022

Policy No: SP2002211882-01
Nature of Claim: OD

Claim No: 202222006507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML8057S**
Make & Model: TOYOTA WISH, 2.0 (A) Engine No: 3ZRA505977
Reg. Date: 12/08/2010 (Man. Year: 2010) Chassis No: JTDGJ20W805002867
Colour: Silver Odometer: 201332 km
Engine Capacity: 1987 cc
Market Value/New Car Price: S\$36,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,911.20	3,718.50	2,192.70	37.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	800.00	330.00	29.20
Paintwork Labour	900.00	800.00	100.00	11.11
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,941.20	5,318.50	2,622.70	33.03
Approved Total (Overridden) (\$\$)		4,250.00		
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	7,341.20	3,650.00	3,691.20	50.28
+ GST 7.00/8.00% (\$\$)	513.88	292.00	221.88	43.18
Nett Amount (\$\$)	7,855.08	3,942.00	3,913.08	49.82

INSPECTION

Date of Assignment: 22/09/2022 Present Location: Success United Pte Ltd (HQ)
Date Inspected: 22/09/2022 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	M1-MPV	TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML8057S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	350.00 F	*350.00 F
2	2		*FRONT BONNET HINGE L/R (WCP)	Not Necessary	116.00 F	*- F
3	1		*FRONT BONNET STAND (WCP)	Not Necessary	25.00 F	*- F
4	1		*FRONT BONNET INSULATOR (WCP)	Not Necessary	180.00 F	*- F
5	1		*FRONT BONNET MECHANISM LOCK (WCP)	Damaged	80.00 F	*80.00 F
6	1		*FRONT BONNET MECHANISM LOCK CABLE (WCP)	Not Necessary	75.00 F	*- F
7	1		*FRONT BONNET WEATHERSTRIP (WCP)	Not Necessary	45.00 F	*- F
8	1		*FRONT TOYOTA LOGO (WCP)	Necessary	45.00 F	*45.00 F
9	1		*FRONT FENDER LH (WCP)	Buckled	320.00 F	*320.00 F
10	2		*HEADLAMP ASSY L/R (WCP)	Cracked	900.00 F	*900.00 F
11	2		*HEADLAMP BRACKET L/R (WCP)	Not Necessary	96.00 F	*- F
12	1		*FRONT BUMPER ASSY (WCP)	Distorted	300.00 F	*300.00 F
13	1		*FRONT BUMPER INNER SPONGE (WCP)	Cracked	90.00 F	*90.00 F
14	1		*FRONT BUMPER LOWER AIR GRILLE (WCP)	Not Necessary	100.00 F	*- F
15	2		*FRONT BUMPER SIDE AIR GRILLE L/R (WCP)	Deformed	100.00 F	*100.00 F
16	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	180.00 F	*180.00 F
17	1		*FRONT GRILLE (WCP)	Cracked	165.00 F	*165.00 F
18	1		*HORN (WCP)	Not Necessary	60.00 F	*- F
19	1		*RADIATOR SUPPORT PANEL ASSY (WCP)	Repair	620.00 F	*- F
20	1		*RADIATOR SUPPORT PANEL TOP COVER GARNISH (WCP)	Deformed	80.00 F	*80.00 F
21	1		*CENTER BRACE PANEL (WCP)	Bent	55.00 F	*55.00 F
22	1		*RADIATOR ASSY (WCP)	Not Necessary	620.00 F	*- F
23	1		*RADIATOR TOP MOUNTING RH (WCP)	Not Necessary	20.00 F	*- F
24	1		*AIRCON CONDENSER (WCP)	Bent	580.00 F	*580.00 F
25	1		*BATTERY HOLDER (WCP)	Bent	40.00 F	*40.00 F
26	1		*FRONT BONNET STAND CLIP	Not Necessary	20.00 FS	*- FS
27	1		*FRONT BONNET INSULATOR CLIP	Not Necessary	20.00 FS	*- FS
28	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
29	1		*RADIATOR SUPPORT TOP COVER GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
Report was unsubmitted during this print-out.						

5/30/23, 3:24 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*FRONT NUMBER PLATE WITH FRAME	Cracked	45.00 FS	*45.00 FS
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					5,387.00	3,390.00
+ Margin on L,N Items 10.00/10.00% (S\$)					524.20	328.50
Total Parts (S\$)					5,911.20	3,718.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY & RESPRAY PAINTING ON BONNET, BUMPER, FENDER LH, SUPPORT PANEL	New	900.00	800.00
Labour Items				
2	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	30.00
3	TO REMOVE , REINSTAL AIRCON PARTS, VACUUM, REFILL GAS.	New	200.00	120.00
4	TO REMOVE, REPAIR & REPLACED DAMAGED BODY PARTS, REALIGN BODYWORK, & WHERE CONSISTENT TO THE ACCIDENT	New	850.00	650.00
Gross Labour Cost (\$\$)			2,030.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >