

Success United Pte Ltd (Co.Reg.No.200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

Xiao Chen.

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU220106
Policy No:	SP2002211882-01	Date of Loss:	02/09/2022
Vehicle Reg. No.:	SML8057S	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Eeong Electrical Engineering Pte Ltd	Contact No:	+6590998367
Driver:	Lee Xiew Eeong		
Make/Model:	TOYOTA WISH, 2.0 (A)	Vehicle Reg. Date:	12/08/2010
Vehicle Colour:	Grey		
Engine No:	3ZRA505977	Chassis No:	JTDGJ20W805002867
Odometer:	201332 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		

Description of Accident/Loss I (SML8057S) WAS TRAVELLING ALONG BKE TOWARDS PIE. VEHICLE B (SLD9387L) AHEAD SLOWED DOWN AND STOPPED. I TRIED TO BRAKE BUT COULD NOT STOP COMPLETELY. MY VEHICLE THEN COLLIDED WITH THE REAR OF VEHICLE B.

Present Location: **SUCCESS UNITED PTE LTD (HQ)**

COST OF CLAIMS

	Amount
Parts	5,911.20
Miscellaneous Items	0.00
Labour	1,130.00
Paintwork Labour	900.00
Towing	0.00
Calculated Gross Total (S\$)	7,941.20
- Excess (S\$)	600.00
(S\$)	7,341.20
+ GST 7.00% (S\$)	513.88
Nett Amount (S\$)	7,855.08

This claim is handled by: LAW YI TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2022)
 Parts: M1-MPV TOYOTA WISH 2.0 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Success United Pte Ltd/SML8057S/21/09/2022 16:06
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>Perked</i>	0.00	0.00	*350.00 F ✓
2	2		*FRONT BONNET HINGE L/R <i>seen</i>	0.00	0.00	*116.00 F +
3	1		*FRONT BONNET STAND <i>seen</i>	0.00	0.00	*25.00 F +
4	1		*FRONT BONNET INSULATOR <i>seen</i>	0.00	0.00	*180.00 F +
5	1		*FRONT BONNET MECHANISM LOCK <i>Perked</i>	0.00	0.00	*80.00 F ✓
6	1		*FRONT BONNET MECHANISM LOCK CABLE <i>seen</i>	0.00	0.00	*75.00 F +
7	1		*FRONT BONNET WEATHERSTRIP <i>seen</i>	0.00	0.00	*45.00 F ✓
8	1		*FRONT TOYOTA LOGO <i>seen</i>	0.00	0.00	*45.00 F ✓
9	1		*FRONT FENDER LH <i>Perked</i>	0.00	0.00	*320.00 F ✓
10	2		*HEADLAMP ASSY L/R <i>Perked</i>	0.00	0.00	*900.00 F ✓
11	2		*HEADLAMP BRACKET L/R <i>seen</i>	0.00	0.00	*96.00 F +
12	1		*FRONT BUMPER ASSY <i>Perked</i>	0.00	0.00	*300.00 F ✓
13	1		*FRONT BUMPER INNER SPONGE <i>Perked</i>	0.00	0.00	*90.00 F ✓
14	1		*FRONT BUMPER LOWER AIR GRILLE <i>seen</i>	0.00	0.00	*100.00 F +
15	2		*FRONT BUMPER SIDE AIR GRILLE L/R <i>Perked</i>	0.00	0.00	*100.00 F ✓
16	1		*FRONT BUMPER REINFORCEMENT <i>Perked</i>	0.00	0.00	*180.00 F ✓
17	1		*FRONT GRILLE <i>Perked</i>	0.00	0.00	*165.00 F ✓
18	1		*HORN <i>seen</i>	0.00	0.00	*60.00 F +
19	1		*RADIATOR SUPPORT PANEL ASSY <i>Perked</i>	0.00	0.00	*620.00 F +
20	1		*RADIATOR SUPPORT PANEL TOP COVER GARNISH <i>Perked</i>	0.00	0.00	*80.00 F ✓
21	1		*CENTER BRACE PANEL <i>Perked</i>	0.00	0.00	*55.00 F ✓
22	1		*RADIATOR ASSY <i>seen</i>	0.00	0.00	*620.00 F +
23	1		*RADIATOR TOP MOUNTING RH <i>seen</i>	0.00	0.00	*20.00 F +
24	1		*AIRCON CONDENSER <i>Perked</i>	0.00	0.00	*580.00 F ✓
25	1		*BATTERY HOLDER <i>Perked</i>	0.00	0.00	*40.00 F ✓
26	1		*FRONT BONNET STAND CLIP <i>seen</i>	0	0.00	*20.00 FS +
27	1		*FRONT BONNET INSULATOR CLIP <i>seen</i>	0	0.00	*20.00 FS +
28	1		*FRONT BUMPER CLIP <i>seen</i>	0	0.00	*30.00 FS ✓
29	1		*RADIATOR SUPPORT TOP COVER GARNISH CLIP <i>seen</i>	0	0.00	*30.00 FS ✓
30	1		*FRONT NUMBER PLATE WITH FRAME <i>Perked</i>	0	0.00	*45.00 FS ✓

F=Franchise part, S=SpcNett.

Sub Total (\$\$) 5,387.00
 + Margin on L,N Items 10.00% (\$\$) 524.20
 Total Parts (\$\$) 5,911.20

Success United Pte Ltd/SML8057S/21/09/2022 16:06. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

3285
 +10%: 3613.50

S.N: 105

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

No	Particulars	Lab.Type	Amount
1	TO PUTTY & RESPRAY PAINTING ON BONNET, BUMPER, FENDER LH, SUPPORT PANEL	New	900.00 ⁸⁰⁰

Labour Items

2	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00 ³⁰
3	TO REMOVE, REINSTAL AIRCON PARTS, VACUUM, REFILL GAS.	New	200.00 ¹²⁰
4	TO REMOVE, REPAIR & REPLACED DAMAGED BODY PARTS, REALIGN BODYWORK, & WHERE CONSISTENT TO THE ACCIDENT	New	850.00 ⁶⁵⁰

1600

Gross Labour Cost (\$\$)

2,030.00

Success United Pte Ltd/SML8057S/21/09/2022 16:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Admin
w/s 22/09/22

06 days

Not Authored

Exen \$600.

total: 5318.50

w/s: 4250 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

D