

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009340/AQY3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00238792101

Claimant Vehicle No : SMU2522H **Insured Vehicle No :** SMG6604C

Date of Loss: 20/09/2022 Nature of Claim: TP Claim No: SNM22D206734/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU2522H**

Make & Model: HYUNDAI ACCENT, 1.3 (A) Engine No: G4LCKU240712

Reg. Date: 04/08/2020 (Man. Year: 2019) Chassis No: KMHCU41BTKU481104

Colour: Red Odometer: 165258 km

Engine Capacity: 1368 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/70 R14C Rear Tyre Size: 175/70 R14C

Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm

Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,258.00	16,791.20	15,466.80	47.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,810.00	5,560.00	6,250.00	52.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,068.00	22,351.20	21,716.80	49.28
Approved Total (Overridden) (S\$)		17,800.00		
(S\$)	44,068.00	17,800.00	26,268.00	59.61
+ GST 8.00/8.00% (S\$)	3,525.44	1,424.00	2,101.44	59.61
Nett Amount (S\$)	47,593.44	19,224.00	28,369.44	59.61

INSPECTION

Date of Assignment: 21/09/2022

Date Inspected: 22/09/2022 Inspected At: 8 KAKI BUKIT AVE 4
#05-27 PREMIER
SINGAPORE 415875
Repairer: A-Tec Automotive Pte Ltd (Kaki Bukit)

Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	HYUNDAI ACCENT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU2522H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Deformed	970.00 F	*468.00 FL
2	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	480.00 F	*289.00 FL
3	1		*FRONT BUMPER ABSORBER FOAM	Not Necessary	150.00 F	*- FL
4	1		*SET FRONT BUMPER RETAINER	Necessary	32.00 F	*32.00 FL
5	1		*SET FRONT BUMPER BRACKET	Necessary	32.00 F	*32.00 FL
6	1		*FRONT BUMPER GRILLE UPPER	Cracked	950.00 F	*236.00 FL
7	1		*FRONT BUMPER GRILLE HYUNDAI LOGO	Necessary	49.00 F	*49.00 FL
8	1		*FRONT BUMPER GRILLE LOWER	Deformed	580.00 F	*158.00 FL
9	1		*FRONT BUMPER TOW CAP	Deformed	25.00 F	*25.00 FL
10	1		*FRONT HEADLAMP RH	Cracked	1,600.00 F	*1,600.00 FL
11	1		*FRONT HEADLAMP LH	Not Necessary	1,600.00 F	*- FL
12	1		*FRONT FOG LAMP RH	Cracked	250.00 F	*250.00 FL
13	1		*FRONT FOG LAMP LH	Cracked	250.00 F	*250.00 FL
14	1		*FRONT BONNET ASSY	Dented	1,200.00 F	*1,200.00 FL
15	1		*FRONT BONNET LATCH	Not Necessary	200.00 F	*- FL
16	1		*FRONT FENDER ASSY RH	Dented	700.00 F	*483.00 FL
17	1		*FRONT DRIVER DOOR ASSY (NPA)	Repair	0.00 F	*- FL
18	1		*FRONT RADIATOR SUPPORT PANEL ASSY	Distorted	1,150.00 F	*781.00 FL
19	1		*FRONT RADIATOR SUPPORT PANEL COVER	Deformed	350.00 F	*65.00 FL
20	1		*FRONT RADIATOR ASSY	Distorted	950.00 F	*950.00 FL
21	1		*FRONT RADIATOR FAN MOTOR ASSY	Cracked	780.00 F	*780.00 FL
22	1		*FRONT CONDENSER ASSY	Distorted	920.00 F	*920.00 FL
23	1		*FRONT THERMOSTAT HOUSING UPPER	Not Necessary	100.00 F	*- FL
24	1		*FRONT WIPER MOTOR	Deformed	320.00 F	*89.00 FL
25	1		*SET FRONT BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
26	1		*SET FRONT RADIATOR SUPPORT PANEL CLIPS	Necessary	100.00 FS	*20.00 FS
27	1		*SET FRONT VEHICLE PLATE	Bent	150.00 FS	*60.00 FS
28	1		*CONDENSER AIRCON GAS	Necessary	80.00 FS	*30.00 FS
29	1		*RADIATOR COOLANT	Necessary	80.00 FS	*50.00 FS
30	1		*REAR BUMPER ASSY	Distorted	970.00 F	*545.00 FL
31	1		*SET REAR BUMPER RETAINER	Necessary	35.00 F	*35.00 FL
32	1		*SET REAR BUMPER BRACKET	Necessary	35.00 F	*35.00 FL
33	1		*REAR BUMPER REINFORCEMENT BAR	Distorted	480.00 F	*376.00 FL
34	1		*SET REAR BUMPER REFLECTOR	Cracked	300.00 F	*300.00 FL
35	1		*REAR BUMPER TOP GARNISH	Deformed	450.00 F	*182.00 FL
36	1		*REAR TAILGATE ASSY	Distorted	1,200.00 F	*1,200.00 FL
37	1		*SET REAR TAILGATE HINGE	Bent	250.00 F	*250.00 FL
38	1		*REAR TAILGATE OUTER GARNISH	Deformed	460.00 F	*236.00 FL
39	1		*REAR TAILGATE INNER GARNISH	Deformed	520.00 F	*185.00 FL
40	1		*REAR TAILGATE ACCENT EMBLEM	Necessary	150.00 F	*45.00 FL
41	1		*REAR TAILGATE HYUNDAI LOGO	Necessary	150.00 F	*50.00 FL
42	1		*REAR TAILLAMP RH	Cracked	900.00 F	*389.00 FL
43	1		*REAR TAILLAMP LH	Cracked	900.00 F	*389.00 FL
44	1		*SET REAR VEHICLE PLATE LAMP	Not Necessary	100.00 F	*- FL
45	1		*REAR QUARTER PANEL LH INNER	Repair	1,100.00 F	*- FL
46	1		*REAR QUARTER PANEL RH INNER	Buckled	1,000.00 F	*850.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR QUARTER PANEL LH INNER	Buckled	1,600.00 F	*1,600.00 FL
48	1		*REAR QUARTER PANEL RH INNER	Buckled	1,600.00 F	*1,600.00 FL
49	1		*REAR END PANEL ASSY	Distorted	780.00 F	*499.00 FL
50	1		*REAR TAIL LAMP PANEL RH	Distorted	250.00 F	*250.00 FL
51	1		*REAR TAIL LAMP PANEL LH	Distorted	250.00 F	*250.00 FL
52	1		*REAR LUGGAGE FLOOR PANEL	Distorted	1,250.00 F	*896.00 FL
53	1		*REAR LUGGAGE INNER TRIM CENTER	Torn	170.00 F	*170.00 FL
54	1		*REAR LUGGAGE INNER TRIM LH	Crumpled	180.00 F	*180.00 FL
55	1		*REAR LUGGAGE INNER TRIM RH	Crumpled	180.00 F	*180.00 FL
56	1		*REAR SPARE TYRE BRACKET FOAM	Deformed	50.00 F	*50.00 FL
57	1		*REAR FENDER LINER RH	Deformed	285.00 F	*195.00 FL
58	1		*REAR FENDER LINER LH	Deformed	285.00 F	*195.00 FL
59	1		*REAR EXHAUST PIPE MUFFLER	Repair	660.00 F	*- FL
60	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
61	1		*REAR VEHICLE PLATE	Bent	150.00 FS	*60.00 FS
62	1		*REAR PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
63	1		*REAR SPARE TYRE	Not Necessary	150.00 FS	*- FS
64	1		*SET REAR REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
65	1		*SET REAR REVERSE CAMERA	Damaged	650.00 FS	*380.00 FS
66	1		*SET REAR TAIL LAMP CLIP	Necessary	100.00 FS	*40.00 FS
67	1		*SET REAR LUGGAGE COMPARTMENT TRIM CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	32,258.00	20,749.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,957.80
Total Parts (\$\$)	32,258.00	16,791.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT ,WELD ,STRAIGHTEN AFFECTED AREAS AND REPLACE DAMAGED PARTS	New	3,500.00	3,000.00
2	TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS ,JOB ALLOWANCE	New	2,800.00	2,000.00
3	TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS	New	500.00	120.00
4	TO REMOVE AND INSTALL FRONT BUMPER ASSY	New	280.00	0.00
5	TO REMOVE AND INSTALL FRONT HEADLAMPS AND FOG LAMPS	New	280.00	30.00
6	TO REMOVE AND INSTALL FRONT RADIATOR ASSY AND FAN MOTOR	New	280.00	60.00
7	TO REMOVE AND INSTALL FRONT SUPPORT PANEL	New	280.00	0.00
8	TO REMOVE AND INSTALL FRONT CONDENSER ASSY	New	280.00	60.00
9	TO REMOVE AND INSTALL FRONT WATER LEAK	New	280.00	0.00
10	TO REMOVE AND INSTALL FRONT FENDER ASSY	New	280.00	0.00
11	TO REMOVE AND INSTALL FRONT BONNET ASSY	New	280.00	0.00
12	TO REMOVE AND INSTALL REAR QUARTER PANEL ASSY	New	280.00	0.00
13	TO REMOVE AND INSTALL REAR BUMPER ASSY	New	280.00	0.00
14	TO REMOVE AND INSTALL REAR INNER TRIMS	New	280.00	80.00
15	TO REMOVE AND INSTALL REAR TAILLAMPS	New	280.00	30.00
16	TO REMOVE AND INSTALL REAR TAILGATE ASSY	New	280.00	0.00
17	TO REMOVE AND INSTALL REAR END PANEL ASSY	New	280.00	0.00
18	TO REMOVE AND INSTALL REAR REVERSE CAMERA AND SENSOR	New	280.00	100.00
19	TO REMOVE AND INSTALL REAR EXHAUST SYSTEM	New	280.00	80.00
20	TO CONDUCT CENTRAL DOOR LOCK SYSTEM	New	180.00	0.00
21	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
Gross Labour Cost (\$\$)			11,810.00	5,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >