

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009341/AQY3E2
Date: 20/12/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00144612201
Claimant Vehicle No :	SLR7976B	Insured Vehicle No :	SLQ2510A
Date of Loss:	20/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206738/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR7976B
Make & Model:	HONDA VEZEL, 1.5 (A)
Reg. Date:	29/08/2017 (Man. Year: 2016)
Colour:	Blue
Engine Capacity:	1496 cc
Market Value/New Car Price:	N/A
Sum Insured (S\$):	Market Value/New Car Price
Engine No:	L15B4408889
Chassis No:	RU11208887
Odometer:	71762 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Wanli 6 mm	Rear Left Side:	Wanli 6 mm
Front Right Side:	Wanli 6 mm	Rear Right Side:	Wanli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,391.28	4,445.04	1,946.24	30.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,490.00	850.00	36.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,731.28	5,935.04	2,796.24	32.03
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	8,731.28	4,700.00	4,031.28	46.17
+ GST 7.00/7.00% (S\$)	611.19	329.00	282.19	46.17
Nett Amount (S\$)	9,342.47	5,029.00	4,313.47	46.17

INSPECTION

Date of Assignment:	22/09/2022		
Date Inspected:	23/09/2022	Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR7976B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	801.70 FL	*801.70 FL
2	1		*FRONT BUMPER LOWER LID GARNISH	Cut	381.00 FL	*381.00 FL
3	1		*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	41.20 FL	*20.60 FL
4	1		*FRONT RH DOOR	Repair	1,080.50 FL	*- FL
5	1		*FRONT RH DOOR FRAME BLACK TAPE	Not Necessary	33.00 FL	*- FL
6	1		*FRONT RH FENDER	Dented	580.00 FL	*580.00 FL
7	1		*FRONT RH FENDER ARCH GARNISH	Deformed	220.00 FL	*220.00 FL
8	1		*FRONT RH FENDER INNER SHIELD	Deformed	130.00 FL	*130.00 FL
9	1		*FRONT RH HEADLAMP	Cracked	1,784.50 FL	*1,784.50 FL
10	1		*FRONT RH HEADLAMP LOWER BRACKET	Not Necessary	35.00 FL	*- FL
11	1		*FRONT RH KNUCKLE ARM	Damaged	390.00 FL	*390.00 FL
12	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	190.00 FL	*190.00 FL
13	1		*FRONT RH LOWER ARM	Bent	371.00 FL	*371.00 FL
14	1		*FRONT RH LOWER ARM BALL JOINT	Not Necessary	98.70 FL	*- FL
15	1		*FRONT RH SHOCK ABSORBER	Not Necessary	502.00 FL	*- FL
16	1		*FRONT RH SPORT RIM	Cut	650.40 FS	*450.00 FS
17	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
18	1		*SET FRONT RH FENDER ARCH GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
19	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*FRONT RH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,719.00	5,418.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,327.72	973.76
Total Parts (\$)	6,391.28	4,445.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	60.00	30.00
2	TO REMOVE,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM, KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB,DRIVE SHAFT ,ANTI -ROLL BAR ,TOP -ARM AND STEERING RACK AND PINION	New	280.00	200.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	500.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	80.00
Gross Labour Cost (\$\$)			2,340.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >