10/31/22, 3:51 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI22009343/GVY3M4

Date: 31/10/2022

REFERENCE

Reg. Date:

No:

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle

SHB4019R

•

Insured Vehicle No: SMD5756U

Date of Loss: 21/09/2022

Nature of Claim:

Claim No: DM22HO01633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB4019R

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)

Engine No: G4LEKU419199

0 km

28/01/2021 (Man. Year: 2019)

Odometer:

Chassis No:

KMHC851CVLU192555

Yes

Colour: Blue

Engine Capacity:

Market Value/New Car Price:

1580 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,779.44	3,249.76	1,529.68	32.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,820.00	1,540.00	280.00	15.38
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,599.44	4,789.76	1,809.68	27.42
	Approved Total (Overridden) (S\$)		3,800.00		
	(S\$)	6,599.44	3,800.00	2,799.44	42.42
	+ GST 7.00/7.00% (S\$)	461.96	266.00	195.96	42.42
	Nett Amount (S\$)	7,061.40	4,066.00	2,995.40	42.42

INSPECTION

Date of Assignment: 22/09/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 22/09/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Oct 2022)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB4019R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	481.10 FL	*- FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	35.00 FL	*- FL
3	1		*FRONT BUMPER GRILLE LH	Scratched	93.45 FL	*93.45 FL
4	1		*FRONT FENDER LH	Repair	588.80 FL	*- FL
5	1		*FRONT FENDER EMBLEM LH	Necessary	26.60 FL	*26.60 FL
6	1		*FRONT FENDER SHIELD LH	Not Necessary	164.70 FL	*- FL
7	1		*FRONT DAY LIGHT LH	Not Necessary	642.50 FL	*- FL
8	1		*HEAD LAMP LH	Scratched	2,110.30 FL	*2,110.30 FL
9	1		*FRONT WING MIRROR ASSY LH	Cut	1,391.70 FL	*1,391.70 FL
10	1		*FRONT WHEEL COVER LH	Scratched	346.40 FL	*346.40 FL
11 E-Er	1	nart S-SncA	*FRONT DOOR COMFORT LOGO STICKER lett. L=ListItemDisc.	Necessary	75.00 FS	*75.00 FS
1 -1 16	111011130	part. 0-Opciv	iett. L-Listiteriibisc.	Sub Total (S\$)	5,955.55	4,043.45
	- List Item Discount on L Items 20.00/20.00% (S\$)					793.69
				Total Parts (S\$)	4,779.44	3,249.76
			Report was unsubmitted durin	g this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	900.00	700.00
2	SPRAY PAINT	New	800.00	750.00
3	CHECK LIGHTING	New	60.00	30.00
4	RESET FRONT WHEEL ALIGNMENT	New	60.00	60.00
		Gross Labour Cost (S\$)	1,820.00	1,540.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >