

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009345/KNY3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00003922203
Claimant Vehicle No :	SDS2661G	Insured Vehicle No :	CB3996K
Date of Loss:	15/09/2022	Nature of Claim: TP	Claim No: SNM22D206619/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS2661G	Engine No:	FB20CE49074
Make & Model:	SUBARU IMPREZA, 2.0 (A)	Chassis No:	JF1GT7KL5KG064724
Reg. Date:	27/09/2019 (Man. Year: 2018)	Odometer:	60838 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R17	Rear Tyre Size:	205/50 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,333.76	1,553.44	2,780.32	64.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,210.00	1,570.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,113.76	2,763.44	4,350.32	61.15
+ GST 8.00/8.00% (S\$)	569.10	221.08	348.02	61.15
Nett Amount (S\$)	7,682.86	2,984.52	4,698.34	61.15

INSPECTION

Date of Assignment:	22/09/2022		
Date Inspected:	23/09/2022	Inspected At:	Spark Car Care @ Braddell (HQ) 205 BRADDELL RD Singapore 579701
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 May 2023)	
Parts:	N/A	SUBARU IMPREZA 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS2661G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,050.00 FL	*1,050.00 FL
2	1		*TAILGATE RUBBER	Serviceable	115.00 FL	*- FL
3	1		*TAILGATE INNER TRIMBOARD	Serviceable	195.00 FL	*- FL
4	1		*TAILGATE LOCK	Repair	185.00 FL	*- FL
5	2		*TAILGATE LAMP	Serviceable	410.00 FL	*- FL
6	2		*TAILGATE ABSORBER	Serviceable	350.00 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Serviceable	185.00 FL	*- FL
8	1		*TAILGATE EMBLEM	Necessary	85.00 FL	*58.90 FL
9	1		*TAILGATE SUBARU WORDING	Necessary	115.00 FL	*62.90 FL
10	1		*TAILGATE SYMMETRICAL AWD WORDING	Necessary	115.00 FL	*60.50 FL
11	1		*TAILGATE IMPREZA WORDING	Necessary	45.00 FL	*45.00 FL
12	1		*TAILGATE EYE SIGHT WORDING	Necessary	50.00 FL	*50.00 FL
13	1		*REAR BUMPER	Cracked	454.00 FL	*454.00 FL
14	10		*REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Serviceable	48.20 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	46.00 FL	*- FL
17	1		*REAR BUMPER SPONGE	Serviceable	205.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Repair	245.00 FL	*- FL
19	1		*REAR BUMPER TOW COVER	Dented	18.00 FL	*18.00 FL
20	2		*REAR BUMPER REFLEXOR LAMP	Serviceable	66.00 FL	*- FL
21	4		*REAR BUMPER SENSOR (NPA)	Serviceable	0.00 FL	*- FL
22	4		*REAR BUMPER BRACKET (NPA)	Repair	0.00 FL	*- FL
23	4		*REAR BUMPER SENSOR RING (NPA)	Serviceable	0.00 FL	*- FL
24	2		*REAR TAILLAMP	Serviceable	770.00 FL	*- FL
25	1		*REAR END PANEL	Repair	295.00 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Serviceable	115.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
28	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*50.00 FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,372.20	1,919.30
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,038.44	365.86
Total Parts (\$\$)					4,333.76	1,553.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT AND WELD /KNOCK & STRAIGHTEN ON ACCIDENT AREA TO REMOVE & REFIT DAMAGE PARTS AND REALIGN THE SAME	New	850.00	400.00
2	TO PUTTY AND SPRAY PAINT REAR BUMPER ,REAR TAILGATE ,REAR END PANEL AND AFFECTED AREA	New	1,000.00	500.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	80.00
5	TO REMOVE AND REFIT REAR WINDSCREEN	New	160.00	120.00
6	TO RUST PROOF THE AFFECTED AREA	New	350.00	30.00
7	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	200.00	60.00
Gross Labour Cost (S\$)			2,780.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >