

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22009349/RVY3Q2**Date:** 22/11/2022REFERENCE

Insured/Claimant: PEH YU XIN Policy No: DMPCSNW00062652201
Date of Loss: 18/09/2022 Nature of Claim: OD Claim No: SNM22D206680/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDL3379C**
Make & Model: HONDA ACCORD, 2.0 (A) Engine No: R20A31800177
Reg. Date: 23/04/2008 (Man. Year: 2008) Chassis No: MRHCP16308P020160
Colour: White Odometer: 0 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$61,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,400.00	4,120.00	1,280.00	23.70
Miscellaneous Items	475.00	335.00	140.00	29.47
Labour	672.00	558.60	113.40	16.87
Paintwork Labour	883.33	912.66	-29.33	-3.32
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,430.33	5,926.26	1,504.07	20.24
Approved Total (Overridden) (S\$)		4,750.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	7,430.33	4,500.00	2,930.33	39.44
+ GST 7.00/7.00% (S\$)	520.12	315.00	205.12	39.44
Nett Amount (S\$)	7,950.45	4,815.00	3,135.45	39.44

INSPECTION

Date of Assignment: 22/09/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected: 22/09/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
Estimated Period of Repair: 10.0 days 6 Marsiling Lane
Singapore 739145

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
Parts:	143	HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDL3379C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		5,400.00 F	*4,120.00 F
F=Franchise part.						
Total Parts (S\$)					5,400.00	4,120.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	475.00	335.00
Sub Total (S\$)			475.00	335.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	883.33	912.66
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	672.00	558.60
Gross Labour Cost (S\$)			1,555.33	1,471.26

Report was unsubmitted during this print-out.

< END OF ESTIMATES >