

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22009355/DWY3Q2**Date:** 24/02/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHA7803D **Insured Vehicle No :** SJB8560T

Date of Loss: 20/09/2022 Nature of Claim: TP Claim No: DMPC2200433H/03/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA7803D**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 2ZRS080843

Reg. Date: 06/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU203568909

Colour: Blue Odometer: 645312 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,643.58	21,343.16	12,300.42	36.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	2,290.00	2,740.00	54.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,673.58	23,633.16	15,040.42	38.89
Approved Total (Overridden) (S\$)		18,900.00		
(S\$)	38,673.58	18,900.00	19,773.58	51.13
+ GST 8.00/8.00% (S\$)	3,093.89	1,512.00	1,581.89	51.13
Nett Amount (S\$)	41,767.47	20,412.00	21,355.47	51.13

INSPECTION

Date of Assignment: 22/09/2022

Date Inspected: 23/09/2022 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Feb 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7803D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Dented	1,264.00 FL	*1,264.00 FL
2	1		*FRONT DOOR HINGE UPPER	Bent	91.20 FL	*91.20 FL
3	1		*FRONT DOOR HINGE LOWER	Bent	91.20 FL	*91.20 FL
4	1		*FRONT DOOR CHECK	Serviceable	153.52 FL	*- FL
5	1		*FRONT DOOR OUTER MOULDING	Serviceable	188.60 FL	*- FL
6	1		*FRONT DOOR WEATHERSTRIP	Serviceable	457.90 FL	*- FL
7	1		*FRONT DOOR RUBBER SEAL	Serviceable	257.00 FL	*- FL
8	1		*MOTOR ASSY ,POWER WINDOW ,FRT ,RH	Not Necessary	941.80 FL	*- FL
9	1		*REGULATOR FRONT DOOR WINDOW FRT ,RH	Not Necessary	228.40 FL	*- FL
10	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Broken	1,728.70 FL	*1,728.70 FL
11	1		*FRONT DOOR ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
12	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
13	1		*ROCKER PANEL OUTER GARNISH	Cut / Broken	576.00 FL	*576.00 FL
14	1		*ROCKER PANEL OUTER	Not Necessary	519.80 FL	*- FL
15	1		*ROCKER PANEL STEP GARNISH (FRONT) (RH)	Not Necessary	156.50 FL	*- FL
16	1		*BONNET	Not Necessary	1,117.93 FL	*- FL
17	1		*INSULATOR HOOD	Not Necessary	398.10 FL	*- FL
18	10		*INSULATOR CLIPS	Not Necessary	36.80 FL	*- FL
19	1		*BONNET RUBBER	Not Necessary	35.50 FL	*- FL
20	1		*FRONT BUMPER COVER	Cut	591.75 FL	*591.75 FL
21	2		*FRT BUMPER LOWER REINFORCEMENT BRACKET LH/RH	Not Necessary	660.00 FL	*- FL
22	2		*FRONT SIDE MEMBER SIDE COVER	Not Necessary	345.00 FL	*- FL
23	1		*LAMP ASSY ,FOG, RH	Not Necessary	920.00 FL	*- FL
24	1		*LAMP ASSY ,FOG, LH	Mtg Broken	920.00 FL	*920.00 FL
25	2		*FRONT BUMPER SIDE RETAINER	Broken / Mtg Cracked	154.00 FL	*154.00 FL
26	1		*UNIT ASSY ,HEADLAMP RH (LED)	Mtg Cracked	3,455.00 FL	*2,637.60 FL
27	1		*UNIT ASSY ,HEADLAMP LH (LED)	Mtg Cracked	3,455.00 FL	*2,637.60 FL
28	2		*FENDER SUB-ASSY ,FRONT LH/RH	Dented	2,223.86 FL	*1,890.60 FL
29	2		*FRONT FENDER SHIELD	Torn	510.00 FL	*510.00 FL
30	2		*FRONT FENDER SHIELD CLIP	Necessary	29.80 FL	*29.80 FL
31	2		*FRONT FENDER HYBRID EMBLEM ,LH /RH	Necessary	173.00 FL	*173.00 FL
32	1		*BRACKET ,FRONT SIDE PANEL ,RH	Not Necessary	86.30 FL	*- FL
33	1		*EXTENSION ,FRONT FENDER ,RH	Not Necessary	47.20 FL	*- FL
34	1		*PROTECTOR ,FRONT FENDER SIDE PANEL ,RH	Not Necessary	113.90 FL	*- FL
35	1		*SEAL FRONT FENDER TO COWL SIDE ,RH	Not Necessary	15.20 FL	*- FL
36	1		*GUSSET ,FRONT FENDER APRON ,LOWER RH	Not Necessary	34.90 FL	*- FL
37	1		*EXTENSION ,FRONT FENDER APRON ,FRONT RH	Not Necessary	23.20 FL	*- FL
38	1		*MEMBER ,FRONT APRON TO COWL SIDE ,UPPER RH	Not Necessary	138.40 FL	*- FL
39	1		*FRONT APRON TO COWL SIDE ,LOWER FRT RH	Not Necessary	82.30 FL	*- FL
40	1		*WIPER SPARE TANK ASSY	Not Necessary	486.70 FL	*- FL
41	1		*WIPER TANK NECK	Not Necessary	89.40 FL	*- FL
42	1		*WIPER TANK MOTOR	Not Necessary	138.00 FL	*- FL
43	2		*FRONT WHEEL RIM	Cut	3,141.10 FL	*3,141.10 FL
44	2		*FRONT WHEEL RIM CAP	Not fitted	379.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*FRONT WHEEL HUB AND BEARING	Damaged	1,527.60 FL	*1,527.60 FL
46	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	637.50 FL	*637.50 FL
47	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	637.50 FL	*637.50 FL
48	1		*FRONT SHOCK ABSORBER (LH)	Distorted	401.80 FL	*401.80 FL
49	1		*FRONT SHOCK ABSORBER (RH)	Distorted	401.80 FL	*401.80 FL
50	2		*ABSORBER TOP MOUNTING	Not Necessary	392.40 FL	*- FL
51	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,764.00 FL	*- FL
52	1		*FRONT DRIVE SHAFT (RH)	Damaged	1,764.00 FL	*1,764.00 FL
53	1		*RACK & PINION ASSY	Damaged	1,634.90 FL	*1,634.90 FL
54	1		*BAR STABILIZER	Distorted	360.00 FL	*360.00 FL
55	1		*LINK ASSY ,FRONT STABILIZER LH	Not Necessary	199.00 FL	*- FL
56	1		*KNUCKLE STEERING RH	Distorted	580.80 FL	*580.80 FL
57	1		*KNUCKLE STEERING LH	Distorted	580.80 FL	*580.80 FL
58	2		*JOINT ASSY ,LOWER BALL ,FRONT (LH/RH)	Not Necessary	399.96 FL	*- FL
59	1		*END SUB-ASSY, TIE ROD ,RH	Distorted	159.30 FL	*159.30 FL
60	1		*END SUB-ASSY, TIE ROD ,LH	Distorted	159.30 FL	*159.30 FL
61	1		*ENGINE UNDER COVER	Not Necessary	457.20 FL	*- FL
62	2		*FRONT FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
63	1		*FRONT TYRE (LH/RH)	O/S Not Necessary / N/S Cut	432.00 FS	*108.00 FS
64	1		*ENGINE CROSS MEMBER	Distorted	2,531.70 FL	*2,531.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	41,852.72	28,296.55
- List Item Discount on L Items 20.00/25.00% (\$\$)	8,209.14	6,953.39
Total Parts (\$\$)	33,643.58	21,343.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	900.00
2	SPRAY PAINTING CHARGE	New	1,600.00	900.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	300.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			5,030.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >