

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009356/DNY3Q2**Date:** 16/01/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00166032201

**Claimant Vehicle
No :** SMP8636A**Insured
Vehicle No :** SNA3746R

Date of Loss: 20/09/2022

Nature of Claim: TP

Claim
No: SNM22D206735/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMP8636A**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU471573

Reg. Date: 21/10/2019 (Man. Year: 2019)

Chassis No: KMHD841CMLU008679

Colour: White

Odometer: 49029 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,679.44	2,636.32	15,043.12	85.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,270.00	1,390.00	3,880.00	73.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,949.44	4,026.32	18,923.12	82.46
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	22,949.44	3,200.00	19,749.44	86.06
+ GST 7.00/7.00% (S\$)	1,606.46	224.00	1,382.46	86.06
Nett Amount (S\$)	24,555.90	3,424.00	21,131.90	86.06

INSPECTION

Date of Assignment: 22/09/2022

Date Inspected: 22/09/2022 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP8636A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BOOTLID	Repair	2,032.20 FL	*- FL	
2	1		*BOOTLID LOCK	Not Necessary	316.20 FL	*- FL	
3	1		*BOOTLID STRIKER LOCK	Not Necessary	49.80 FL	*- FL	
4	1		*BOOTLID SWITCH	Not Necessary	301.40 FL	*- FL	
5	1		*SET BOOTLID STOPPERS	Not Necessary	20.00 FL	*- FL	
6	2		*BOOTLID LAMP LH/RH	Not Necessary	1,473.00 FL	*- FL	
7	1		*BOOTLID HYUNDAI LOGO	Necessary	88.20 FL	*88.20 FL	
8	1		*BOOTLID AVANTE EMBLEM	Necessary	61.20 FL	*61.20 FL	
9	1		*BOOTLID WEATHER STRIP	Not Necessary	308.30 FL	*- FL	
10	1		*BOOTLID INNER TRIM	Not Necessary	420.80 FL	*- FL	
11	1		*TAIL LAMP LH/RH	N/SMtgCracked/O/S	NotNecessary	2,153.60 FL	*676.00 FL
12	2		*TAIL LAMP PANEL LH/RH	Not Necessary	772.40 FL	*- FL	
13	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	151.80 FL	*- FL	
14	1		*REAR BUMPER	Distorted / Mtg Broken	570.80 FL	*498.80 FL	
15	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	99.60 FL	*- FL	
16	1		*REAR BUMPER REFLECTOR LH/RH	O/SNot Necessary/N/SMtgCracked	721.60 FL	*201.50 FL	
17	1		*REAR BUMPER LOWER BLACK GARNISH	Distorted / Mtg Broken	640.00 FL	*340.60 FL	
18	1		*REAR BUMPER SPONGE	Not fitted	544.00 FL	*- FL	
19	1		*REAR REINFORCEMENT BAR	Cracked	1,042.30 FL	*329.00 FL	
20	2		*REAR REINFORCEMENT BAR HOLDER LH /RH	Not Necessary	699.60 FL	*- FL	
21	5		*REAR REINFORCEMENT BAR BRACKET	Not Necessary	325.00 FL	*- FL	
22	1		*REAR BUMPER UNDER COVER	Not Necessary	410.20 FL	*- FL	
23	2		*REAR BUMPER SENSOR	Damaged	446.40 FS	*220.00 FS	
24	2		*REAR BUMPER SENSOR HOLDER	Not Necessary	20.00 FL	*- FL	
25	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	1,140.80 FL	*- FL	
26	1		*REAR KEYLESS SENSOR	Not Necessary	248.60 FL	*- FL	
27	1		*REAR END PANEL	Dented	1,014.30 FL	*485.90 FL	
28	1		*REAR END PANEL TOP GARNISH	Deformed / Cracked	298.40 FL	*189.20 FL	
29	1		*SPARE WHEEL PANEL	Not Necessary	1,782.30 FL	*- FL	
30	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	572.40 FL	*- FL	
31	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	592.00 FL	*- FL	
32	1		*REAR EXHAUST PIPE	Not Necessary	1,672.00 FL	*- FL	
33	1		*REAR EXHAUST MOUNTING	Not Necessary	92.00 FL	*- FL	
34	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	294.00 FL	*- FL	
35	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS	
36	1		*BOOTLID LAMP CLIPS	Not Necessary	50.00 FS	*- FS	
37	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS	
38	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS	
39	1		*REAR BUMPER LOWER LID CLIPS	Necessary	50.00 FS	*15.00 FS	
40	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS	
41	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS	
42	1		*REAR NO PLATE & CASING	Cracked / Broken	80.00 FS	*45.00 FS	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 21,865.20 3,210.40

- List Item Discount on L Items 20.00/20.00% (S\$) 4,185.76 574.08

Report was unsubmitted during this print-out.

1/16/23, 12:36 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	17,679.44 2,636.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,800.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,800.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
6	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	150.00	0.00
7	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,270.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >