

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22009357/Eqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 12/12/2022 SINGAPORE 068811 ATTN: OH VALE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SH 7822G Veh. Inspected FBR 3957B Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M04BBN Excess (\$) 0.00 OH VALE 22/09/2022 Assign From Assign Date **Vehicle Particulars & Condition** 2. YAMAHA T150 Make & Model 150 C.C HIDDEN 2020 Engine No. Year of Reg. MH3UG131000001581 RED Chassis No. Colour Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 70/80-17 PIRELLI 4 mm L/H Front Tyre mm 80/90-17 **PIRELLI** R/H Rear Tyre 4 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S 5. **General Information** 17/09/2022 22/09/2022 (05:29 PM) Inspect Date / Time Accident Date HUA CHIN (2000) TRADING MOTOR SVC CENTRE Survey held at 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE

Report Ref No. CS3/ASM22009357/Eqy3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

Estimate Days of Repair

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

ESTIMATED NORMAL PERIOD FOR REPAIR:

Inspected By

5b.

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

3 Working Days