

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.sg
GST:M9-0009639-E RCB NO:06470300B

22.09.22 1015
Surveyed at hrs
Rick - 8468 2802 rick.teofs@axa.com.sg
Claim No: CH:
Authorized: Yes / No
Checked / B4 / After
P/P L/S CTL TL R/DAY: 7 w/ly
OD TP W/P MV INVTG

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
ROBINSON ROAD
PO BOX 1094
SINGAPORE 902144

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department
Your Ref No: SKR3108D
Claim Type: Own Damage
Accident Date: 20/09/2022

Estimate No: MC1902998
Date: 21 Sep 2022
Policy No: GA523075
Veh Reg No: SKR3108D
Make/Model: M.BENZ E 250 CGI
XS: \$1,600.00
52MD4BFN/cynthia Loh

Estimate Repair Cost to Vehicle No : SKR3108D

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET		1 PC	0.0000	✓
2 FRONT BONNET EMBLEM		1 PC	0.0000	✓
3 FRONT BONNET RUBBER		1 PC	0.0000	✓
4 FRONT BONNET SPRING STOPPER LH & RH		2 PC	0.0000	✓
5 FRONT BONNET INSULATOR CLIPS		12 PC	0.0000	✓
6 FRONT BONNET LOCK LH & RH		2 PC	0.0000	✓
7 FRONT BONNET LOCK CABLE LH & RH		2 PC	0.0000	?
8 FRONT BONNET LOCK CABLE FRT		1 PC	0.0000	?
9 FRONT BONNET SAFETY HOOK		1 PC	0.0000	✓
10 FRONT BONNET SAFETY HOOK STRIKER		1 PC	0.0000	✓
11 FRONT BONNET HINGE LH & RH		2 PC	0.0000	✓
12 RADIATOR GRILLE W EMBLEM		1 PC	0.0000	✓
13 RADIATOR GRILLE T SUPPORT		1 PC	0.0000	✓
14 FRONT BUMPER		1 PC	0.0000	✓
15 FRONT BUMPER RIVET		6 PC	0.0000	✓
16 FRONT BUMPER NO PLATE GARNISH		1 PC	0.0000	✓
17 FRONT BUMPER LOWER GRILLE		1 PC	0.0000	?
18 FRONT BUMPER INNER BOX CTR		1 PC	0.0000	✓
19 FRONT BUMPER INNER BOX BKT LH		1 PC	0.0000	✓
20 FRONT BUMPER SPONGE		1 PC	0.0000	✓
21 FRONT BUMPER SPONGE LH		1 PC	0.0000	✓
22 FRONT BUMPER REINFORCEMENT		1 PC	0.0000	✓
23 FRONT BUMPER REINFORCEMENT STAY LH		1 PC	0.0000	✓
24 FRONT BUMPER PARKING SENSOR		2 PC	0.0000	✓
25 FRONT BUMPER PARKING SENSOR RING		6 PC	0.0000	✓
26 FRONT BUMPER PARKING SENSOR WIRE HARNESS		1 PC	0.0000	?
27 FOGLAMP LH		1 PC	0.0000	✓
28 FOGLAMP COVER LH		1 PC	0.0000	?
29 HEADLAMP LH & RH		2 PC	0.0000	✓
30 HEADLAMP CTRL UNIT LH		1 PC	0.0000	?
31 HEADLAMP WASHER COVER LH		1 PC	0.0000	✓
32 HEADLAMP WASHER NOZZLE LH		1 PC	0.0000	✓
33 HEADLAMP WASHER HOSE		1 PC	0.0000	?
34 HEADLAMP FRAME LH		1 PC	0.0000	✓
35 HEADLAMP FRAME STRUT LH		1 PC	0.0000	✓
36 WASHER TANK		1 PC	0.0000	?
37 INTERCOOLER		1 PC	0.0000	?
38 AIR CON CONDENSER		1 PC	0.0000	?
39 RADIATOR		1 PC	0.0000	?
40 RADIATOR AIR GUIDE TOP		1 PC	0.0000	✓

Zila
Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
ROBINSON ROAD
PO BOX 1094
SINGAPORE 902144

TEL: 63387288 FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: SKR3108D

Claim Type: Own Damage

Accident Date: 20/09/2022

Estimate No: MC1902998

Date: 21 Sep 2022

Policy No: GA523075

Veh Reg No: SKR3108D

Make/Model: M.BENZ E 250 CGI

Estimate Repair Cost to Vehicle No : SKR3108D

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
41 RADIATOR AIR GUIDE BTM		1 PC	0.0000 ✓	
42 RADIATOR SUPPORT PANEL <i>sub</i>		1 PC	0.0000 ✓	
43 RADIATOR SUPPORT PANEL TOP COVER <i>mm</i>		1 PC	0.0000 ✓	
44 AIR INTAKE HOSE		1 PC	0.0000 ✓	
45 FRONT FENDER LH <i>sub</i>		1 PC	0.0000 ✓	
46 FRONT FENDER BLUE EFFICIENCY LOGO <i>mm</i>		1 PC	0.0000 ✓	
47 FRONT FENDER COWLING FRT LH <i>desu</i>		1 PC	0.0000 ✓	
48 FRONT FENDER COWLIGN RIVET <i>mm</i>		6 PC	0.0000 ✓	
			0.00	
	Add 10%		0.00	0.00
Special Nett				
49 NUMBER PLATE <i>sub</i>		1 PC	0.0000 ✓	
50 RADIATOR COOLANT		1 PC	0.0000 ✓	
51 TYRE LHF - CHECK PRICE <i>70% cut</i>		1 PC	0.0000 ✓	
52 SPORT RIM LHF - CHECK PRICE <i>old damaged</i>		1 PC	0.0000 ✓	
				0.00
LABOUR				
53 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	0.0000	
54 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	0.0000	
55 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	0.0000	
56 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	0.0000	
57 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,HEADLAMP FRAME LH.TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	0.0000	
58 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH,RADIATOR SUPPORT PANEL,HEADLAMP PANEL LH.		1 PC	0.0000	
59 TENDER SCHEME REPAIR COST - LUMP SUM		1 PC	18,000.00	
				18,000.00

Zila
Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
ROBINSON ROAD
PO BOX 1094
SINGAPORE 902144

TEL: 63387288 FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: SKR3108D

Claim Type: Own Damage

Accident Date: 20/09/2022

Estimate No: MC1902998

Date: 21 Sep 2022

Policy No: GA523075

Veh Reg No: SKR3108D

Make/Model: M.BENZ E 250 CGI

Estimate Repair Cost to Vehicle No : SKR3108D

Repair Amount	S\$ 18,000.00
Add GST @ 7%	1,260.00
Total Amount payable	<u>S\$ 19,260.00</u>

TOTAL: SINGAPORE DOLLAR NINETEEN THOUSAND TWO HUNDRED SIXTY ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY


Ah Lim Motor Company
AUTHORISED SIGNATURE