



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 382J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	DAMAGED	175.00	175.00
1	HEADLAMP	DAMAGED	585.00	380.00
1	HEADLAMP RIM COVER	DAMAGED	65.00	65.00
2	FRONT FORK SIDE TUBE ASSY	DAMAGED	1,900.00	960.00
1	FORK UNDER BRACKET	DAMAGED	335.00	255.00
1	FRONT BRAKE DISC	DAMAGED	385.00	285.00
1	FRONT RIM SHAFT	NECESSARY	68.00	68.00
1	FRONT WHEEL RIM	DAMAGED	850.00	600.00
1	HANDLE BAR	DAMAGED	155.00	155.00
1	O/S HANDLE BAR END	DAMAGED	60.00	60.00
1	SET HAND GRIP	NECESSARY	50.00	50.00
1	O/S SIDE MIRROR	DAMAGED	95.00	60.00
1	BRAKE LEVER	DAMAGED	65.00	65.00
1	FRONT O/S SIGNAL	DAMAGED	115.00	115.00
1	O/S SIGNAL HOLDER	DAMAGED	60.00	60.00
1	FUEL TANK COWLING	DAMAGED	320.00	300.00
1	FRONT O/S FOOTREST	DAMAGED	75.00	60.00
1	FRONT O/S FOOTREST BRACKET	DAMAGED	245.00	110.00
1	BRAKE PEDAL	DAMAGED	98.00	98.00
1	REAR O/S FOOTREST	DAMAGED	70.00	60.00
1	RADIATOR	DAMAGED	650.00	350.60
1	O/S SIDE BOARD	DAMAGED	130.00	130.00
1	REAR O/S SIGNAL	DAMAGED	105.00	105.00
1	REAR FENDER	NOT NECESSARY	95.00	-
	LESS 10% DISCOUNT		-675.10	-456.66
			6,075.90	4,109.94
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	DAMAGED	28.00	28.00
2	FORK OILS (SN)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN)	NECESSARY	56.00	56.00

Report Ref No. CS3/GRB22007302/Tce2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NECESSARY	95.00	60.00
1	SET SIDE SLIDER (SN)	DAMAGED	95.00	95.00
1	REAR BOX (SN)	DAMAGED	280.00	280.00
1	REAR BOX BRACKET (SN)	INTACT	100.00	-
2	BOTTLES COOLANT OIL (SN)	NECESSARY	40.00	40.00
1	FRONT TYRE (DEPRECIATION) (SN)	DAMAGED	300.00	150.00
			1,024.00	739.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	30.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	300.00
			610.00	360.00
GRAND TOTAL			7,709.90	5,208.94

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,150.00
---	--	--	-----------------

Report Ref No. CS3/GRB22007302/Tce2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.