



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM22004807/Tvy3e2-1 Date: 13/10/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	SH 7589E	Veh. Inspected	GBL 2280H
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M041KP	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	22/09/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTFAT35Y30K216559	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R15	FALKEN	6 mm
	L/H Front Tyre	205/55 R15	FALKEN	6 mm
	R/H Rear Tyre	205/55 R15 (D)	FALKEN	6/6 mm
	L/H Rear Tyre	205/55 R15 (D)	FALKEN	6/6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	18/05/2022	Inspection Date	28/09/2022
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days