No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 22010-07/MY / 2022

Date of Report : 17 Sep 2022

Asyraf Almusaddiq Ibnu Reduan C/o No. 1 Kaki Bukit Ave 6 #01-53/55 AutoBay@Kaki Bukit Singapore 417883

# THIRD PARTY SURVEY ACCIDENT HAPPENED ON 16 Jul 2022

Workshop Address : Bluwel Automotive Service Pte Ltd

No.1 Kaki Bukit Ave 6

#01-53/55 AutoBay@ Kaki Bukit

Singapore 417883

As per your instruction dated 19 Jul 2022 with regard to the above matter. We have carried out a physical inspection on the said vehicle our report and findings as follows:

## 1. VEHICLE PARTICULARS

Registration No : SJR 42 R Engine No : L15B72456026

Model : Honda Civic Mileage : 78077 Year / Capacity : 2018/1498 Colour : White

Chassis No : MRHFC1660HT000473

## 2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	:	235/40 R18	Bridgestone	6.00	mm	Sport
REAR O/S	:	235/40 R18	Bridgestone	6.00	mm	Sport
FRONT N/S	:	235/40 R18	Bridgestone	6.00	mm	Sport
REAR N/S	:	235/40 R18	Bridgestone	6.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

#### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 12 working days to complete.

5. Enclosed number of photograph : <u>229</u> copies.

- 6. In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey was done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- 7. Should you discover any discrepancy in the report, please kindly notify us <u>within 2 weeks</u>, or the report will be treated as correct.

### <u>Disclaimer</u>

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No:

SJR 42 R

Report No:

TP/ 22010-07/MY / 2022

SPARE PARTS

<u>SPAR</u>	E PARTS					
Qty	Parts Description	Condition	Workshop's Estimation			ır Revised stimation
	1 :- 4 14					
4	<u>List Items</u>	Danain	ው	E04.00	•	
1 2	Bonnet Front hoodlamps	Repair	\$	581.30	\$	2250 40 . /
	Front humber reinforcement X 0 V 0	Damage	\$ \$	2258.40	\$	2258.40 🗸
1 1	Front bumper reinforcement X SVC	Damage	Þ	518.20	\$	518.20
1	Front support panel Boot lid	Repair	\$	795.50	\$	464 50 . /
1	Boot lid lock ✓	Damage	Φ	461.50	\$	461.50 <b>✓</b> 101.75 <b>✓</b>
1	Boot lid rubber $\checkmark$	Damage	Ф Ф	101.75 98.80	\$ \$	98.80 ✓
2	Boot lid hinges SVC	Damage Intact	Φ	140.60		90.00 🗸
1	Boot lid logo		φ Φ		\$	21.45./
1	Boot lid logo V	Necessary	Φ	31.45 39.71	\$	31.45
1	Boot lid 'VTEC' emblem	Necessary	Φ	39.71 46.11	\$	39.71 <b>〈</b> 46.11 <b>〈</b>
2	Boot lid VTEC emblem	Necessary	Ф Ф	292.34	Φ Φ	292.34 🗸
1	Boot lid inner trim X SVC	Damage	Ф Ф	178.43	\$ \$ \$	178.43
1	Boot lid outer garnish $\checkmark$	Damage	φ Φ	95.40	э \$	95.40 🗸
2	Rear taillamps $\checkmark$	Damage Damage	ው ው	534.94	φ \$	534.94 🗸
2	Rear taillamp brackets X SVC	Damage	ų P	48.10	φ \$	48.10
1	Rear taillamp panel	Repair	****	140.61	φ	40.10
1	Rear end panel $\checkmark$	Damage	Φ	330.70	\$ \$	330.70 🗸
1	Rear end panel inner garnish	Damage	φ	79.55	\$	79.55 🗸
1	Rear end panel sensor	Damage	\$	80.75	\$	80.75 🗸
1	Rear bumper reinforcement	Damage	\$	360.14	φ	360.14 273
2	Rear bumper side retainers	Damage	\$	52.40	\$ \$ \$ \$ \$	52.40 <b>/</b>
2	Rear bumper reflectors $\checkmark$	Damage	\$	57.40	\$	57.40 <b>✓</b>
2	Rear bumper sensors $\checkmark$	Damage	\$	304.60	\$	304.60 🗸
1	Rear exhaust silencer SVC	Intact	\$	637.45	\$	00 m00 <b>V</b>
1	Rear exhaust silencer moulding SVC	Intact	\$	34.72	\$	
2	Rear fenders	Repair	\$	1874.80	\$	
_		Nopun	<del>\$</del>	10175.65	\$	5970.67 5138.8
	Discount	20.0%	\$	2035.13	\$	1194.13
	2,5553,11		\$	8140.52	\$	4776.54 4111.04
			•		•	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	Special Nett Items					
1	Front grille	Damage	\$	850.00	\$	850.00 650
1	Front sport bumper	Damage	\$	2200.00	\$	2000.00 1600
1	Boot lid top spoiler 🗸	Damage	\$	1800.00	\$	1800.00 1200
1	Rear sport bumper 🗸	Damage	\$	2200.00	\$	2200.00 1600
1	Rear number plate 🗸	Damage	\$ \$ \$	180.00	\$	180.00 80
2	Rear exhaust tail pipes (Accessory) 🗸	Damage	\$	560.00	\$	560.00 400
	· · · · · · · · · · · · · · · · · · ·	-	\$	7790.00	\$	7590.00 5530
	Sı	oare Parts Total	\$	15930.52	\$	12366.54

Page 3

Vehicle No:

**SJR 42 R** 

Report No:

TP/ 22010-07/MY / 2022

LABOUR COST

Spare Parts Total c/f \$ 15930.52 \$  1 To remove and refit damage parts, test for proper functioning and focus of headlamps.  2 To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.  3 To remove and refit inner trims, inner garnishes, to facilitate the repairs.  4 To remove and refit rear bumper sensor.  5 To remove and refit air-con system, refill gas and test for leakages.	LABOU		
1 To remove and refit damage parts, test for proper functioning and focus of headlamps.  2 To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.  3 To remove and refit inner trims, inner garnishes, to facilitate the repairs.  4 To remove and refit rear bumper sensor.  5 To remove and refit air-con system, refill gas and test for leakages.  6 To remove and refit, straighten and re-adjust straighten and replace rear exhaust silencer and mountings.  7 To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced  \$ 200.00 \$		Our Revised Estimation	
functioning and focus of headlamps.  2 To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.  3 To remove and refit inner trims, inner garnishes, to facilitate the repairs.  4 To remove and refit air-con system, refill gas and test for leakages.  5 To remove and refit, straighten and re-adjust straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced  \$ 50.00 \$ \$ 50.00 \$		\$ 12366.54	
damaged lamps and test for proper functioning.  To remove and refit inner trims, inner garnishes, to facilitate the repairs.  To remove and refit rear bumper sensor.  To remove and refit air-con system, refill gas and test for leakages.  To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.  To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  To apply undercoating on the repaired and replaced  \$ 200.00 \$	1	\$ 40.00 20	
facilitate the repairs.  4 To remove and refit rear bumper sensor. \$ 200.00 \$  5 To remove and refit air-con system, refill gas and test for leakages. \$ 180.00 Not test for leakages.  6 To remove and refit, straighten and re-adjust \$ 80.00 Not exhaust pipe and replace rear exhaust silencer and mountings.  7 To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced \$ 200.00 \$	2	\$ 40.00 20	
5 To remove and refit air-con system, refill gas and test for leakages.  6 To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.  7 To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced \$ 200.00 \$	3	\$ 80.00 60	
test for leakages.  6 To remove and refit, straighten and re-adjust \$80.00 Not exhaust pipe and replace rear exhaust silencer and mountings.  7 To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced \$200.00 \$	4	\$ 120.00 40	
exhaust pipe and replace rear exhaust silencer and mountings.  7 To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced \$ 200.00 \$	5	Not Required X	•
straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.  8 To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced \$ 200.00 \$	6	Not Required X	) b
prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.  9 To apply undercoating on the repaired and replaced \$ 200.00 \$	7	\$ 1540.00 <b>800</b>	)
	8	\$ 1760.00 <b>120</b>	0
	9	\$ 120.00 60	)
Total \$ 20640.52 \$		\$ 16066.54 22	200
The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:  \$ 12900.00		11841.04	

SDLS: TWELVE THOUSAND NINE HUNDRED ONLY

-20%: 9500

7 Days

Qualified Appraiser