

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SAJABYAG26A909266

ESTIMATE OF REPAIR

Veh# SKX6753P

Tp ALG
Xiao Tony

Model:

JAGUAR XE

ident Date 22/9/2022

22/12/2015

ocation : PIE (TUAS) BEFORE EG NEO EXIT

3P:

SML3251E (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Dented</i>	3,445.20	✓ 2200	
2	12 pcs	Rear bumper clips <i>n</i>		120.00	✓ 50
3	1 pc	Rear enforcement <i>Dented</i>	1,545.60	✓ 1141	
4	6 pcs	Rear enforcement screw <i>new</i>		60.00	✓
5	1 pc	Rear antenna <i>crushed</i>	210.40	✓	
6	2 pcs	Rear bumper o/s & n/s retainer <i>new</i>	386.60	✓	
7	1 pc	Rear bumper centre retainer <i>crushed</i>	234.40	✓	
8	4pcs	Rear reverse sensor <i>2 pins dented</i>		1480.00	740.
9	1pc	Rear end panel inner <i>Regis</i>			
10	1pc	Rear end panel outer <i>Dented</i>	1,854.60	✓ 1350	
11	1pc	Rear end panel inner trim <i>new</i>	520.40	✓	
12	6pcs	Rear end panel inner trim clips <i>new</i>		60.00	✓
13	2pcs	Rear o/s & n/s tail lamp <i>RH crushed</i>	2,476.80	✓ 1238.40	980.
14	2pcs	Rear o/s & n/s tail lamp seal <i>new</i>	80.00	✓	
15	1pc	Rear boot cover <i>Dented</i>	4,824.80	✓ 3945	
16	1pc	Rear boot cover weatherstrip <i>new</i>	265.70	✓	
17	1pc	Rear boot cover emblem <i>2</i>	235.60	✓	
18	1pc	Rear boot cover 'JAGUAR' emblem	186.70	✓	
19	1pc	Rear boot cover 'X' emblem	106.70	✓	
20	1pc	Rear boot cover '20T' emblem	116.70	✓	
21	2pcs	Rear boot cover o/s & n/s hinges <i>new</i>	365.40	✓	
22	1pc	Rear boot cover lock (Upper) <i>Regis</i>	1,085.60	✓ 786	
23	2 pcs	Rear boot cover o/s & n/s reflector <i>RH crushed</i>	1,816.75	✓ 908	730.
24	1pc	Rear o/s exhaust <i>Regis</i>	4,626.65	✓	
25	4 pcs	Rear exhaust mounting <i>new</i>	320.00	✓	
26	1 pc	Rear exhaust heat shield <i>Dented</i>	645.60	✓ 350	
27	1 pc	Rear regn. no. plate <i>new</i>		35.00	✓

28	1 pc	Rear regn. no. plate bracket	new		30.00	x
29	1 pc	Front bumper	rebuild	3,430.20	2820	
30	10 pcs	Front bumper clips	new		100.00	✓
31	1 pc	Front bumper sponge	cutted	394.20	280.	
32	1 pc	Front o/s bumper sponge	cutted	135.40		
33	1 pc	Front bumper enforcement	Revised	1,596.70	1250	
34	1 pc	Front bumper o/s retainer	new	386.70	x.	
35	1 pc	Front bumper grille (Lower)	Not in	496.60	x.	
36	1 pc	Front bumper o/s fog lamp cover	new	240.60	x.	
37	1 pc	Front grille	cutted	2,436.70	1100	
38	1 pc	Front grille emblem	new	71.70		
39	6 pcs	Front grille clips	new		60.00	20
40	1 pc	Front grille seal	Not in	206.90	x	
41	1 pc	Front o/s head lamp	cutted	4,896.80	3000	
42	1 pc	Front o/s fender	new	860.00	x	
43	1 pc	Front regn. no. plate	galvan		35.00	x
44	1 pc	Front regn. no. plate bracket	galvan		30.00	x
2120650 S/N: 910				Sub Total:	40,502.70	2,010.00 0
1908621					10%	0% 10%
				After Less %:	36,452.43	2,010.00 0
Labour						
1		To dismantle damaged parts, straighten & welding.			2,400.00	1200
2		To spray painting.			1,800.00	1000
3		To remove & replace rear exhaust.			180.00	100
4		To check for fault code and reset electrical system (head lamp)			600.00	150
5		To check wiring.		2570	150.00	60.
6		To re seal anti rust.			100.00	60
				Sub Total:	5,230.00	
				Total:	43,692.43	
				After Less 20%:	34,953.94	

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Adrian Cj
4/s 23/04/22.
09 Days.



AL 8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 2256621
L/S: 18K