

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22009364/KPA3Q2**Date:** 06/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001681581-01
<b>Claimant Vehicle No :</b>	SFZ4177P	<b>Insured Vehicle No :</b>	SKT7352C
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	202222006829

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFZ4177P</b>	Engine No:	28291480312930
Make & Model:	MERCEDES-BENZ GLB200, 1.3 (A)	Chassis No:	W1N2476872W051211
Reg. Date:	26/02/2021 (Man. Year: 2020)	Odometer:	21441 km
Colour:	White		
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,141.00	3,476.00	665.00	16.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	550.00	400.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,091.00</b>	<b>4,026.00</b>	<b>1,065.00</b>	<b>20.92</b>
<b>+ GST 8.00/8.00% (S\$)</b>	407.28	322.08	85.20	20.92
<b>Nett Amount (S\$)</b>	<b>5,498.28</b>	<b>4,348.08</b>	<b>1,150.20</b>	<b>20.92</b>
<b>+ Car Rental (2.0 x S\$100.00/day + 8.00% GST) (S\$)</b>		216.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,566.08</b>		

INSPECTION

Date of Assignment:	22/09/2022	
Date Inspected:	23/09/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	M1-SUV	MERCEDES-BENZ GLB200 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFZ4177P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP CHROME (WCP)	Buckled	190.00 F	*190.00 F
2	1		*REAR BUMPER TOP (WCP)	Mtg Cracked	1,050.00 F	*1,050.00 F
3	1		*REAR BUMPER LOWER (WCP)	Cracked	580.00 F	*580.00 F
4	1		*REAR BUMPER CHROME (WCP)	Dented / Scratched	880.00 F	*880.00 F
5	1		*REAR BUMPER DIFFUSER (WCP)	Serviceable	350.00 F	*- F
6	1		*REAR BUMPER TOP BEAM (WCP)	Cracked	160.00 F	*160.00 F
7	1		*REAR BUMPER LOWER (WCP)	Serviceable	200.00 F	*- F
8	1		*SET REVERSE SENSOR	Missing	250.00 FS	*250.00 FS
9	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*80.00 FS
10	1		*SET RIVET	Not Necessary	60.00 FS	*- FS
					Sub Total (\$\$)	3,800.00 3,190.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	341.00 286.00
					Total Parts (\$\$)	4,141.00 3,476.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REFIT REVERSE SENSOR ONTO NEW BUMPER	New	50.00	50.00
2	TO REPAIR INNER PANEL INCLUDING REPLACEMENT OF PARTS	New	450.00	250.00
3	TO SPRAY REAR BUMPER ,INNER PANEL	New	450.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>950.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >