

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009367/APA3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900115162
Claimant Vehicle No :	SLB1894C	Insured Vehicle No :	SMM7173R
Date of Loss:	09/09/2022	Nature of Claim:	TP
		Claim No:	8898048104SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1894C	Engine No:	3ZRB676592
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600063845
Reg. Date:	30/03/2016 (Man. Year: 2015)	Odometer:	171342 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,344.67	6,562.77	8,781.90	57.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,230.00	2,200.00	64.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,774.67	7,792.77	10,981.90	58.49
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	18,774.67	6,200.00	12,574.67	66.98
+ GST 7.00/7.00% (S\$)	1,314.23	434.00	880.23	66.98
Nett Amount (S\$)	20,088.90	6,634.00	13,454.90	66.98
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,136.00		

INSPECTION

Date of Assignment:	21/09/2022	
Date Inspected:	21/09/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	982.00 FL	*982.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	183.00 FL	*68.00 FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	75.00 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	125.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	495.00 FL	*- FL
6	1		*FRONT BUMPER SIDE SUPPORT BRACKET LH	Bent	225.00 FL	*225.00 FL
7	1		*FRONT BUMPER SIDE SUPPORT BRACKET SPONGE LH	Cracked	159.00 FL	*159.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	284.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP LH	Cracked	379.00 FL	*379.00 FL
10	1		*FRONT BUMPER FOG LAMP BRACKET LH	Not Necessary	140.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP OUTER GARNISH LH	Cut	208.00 FL	*208.00 FL
12	1		*FRONT BUMPER LOWER LIP	Cut	285.00 FL	*285.00 FL
13	1		*FRONT BUMPER LOWER COVER	Not Necessary	322.00 FL	*- FL
14	1		*FRONT GRILLE	Not Necessary	895.00 FL	*- FL
15	1		*FRONT GRILLE LOGO	Not Necessary	1,015.00 FL	*- FL
16	1		*FRONT GRILLE BRACKET	Not Necessary	66.00 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Not Necessary	730.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	320.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL SIDE GUARD GARNISH LH	Not Necessary	218.00 FL	*- FL
20	1		*FRONT SUPPORT PANEL CENTER BEAM	Not Necessary	189.00 FL	*- FL
21	1		*FRONT FENDER LH	Buckled	987.00 FL	*987.00 FL
22	1		*FRONT FENDER INNER COWLING LH	Necessary	572.00 FL	*281.00 FL
23	1		*FRONT FENDER TOP GARNISH LH	Not Necessary	206.00 FL	*- FL
24	1		*FRONT HEADLAMP LH	Cracked	3,512.00 FL	*3,512.00 FL
25	1		*FRONT HEADLAMP LOWER BRACKET LH	Repeated	239.00 FL	*- FL
26	1		*AIR DUCT LH	Not Necessary	139.00 FL	*- FL
27	1		*FRONT RESONATOR TANK	Not Necessary	412.00 FL	*- FL
28	1		*BONNET	Not Necessary	1,983.00 FL	*- FL
29	1		*LH FRONT SHOCK ABSORBER	Not Necessary	537.40 FL	*- FL
30	1		*LH FRONT LOWER ARM	Bent	472.30 FL	*472.30 FL
31	1		*LH FRONT KNUCKLE ARM	Not Necessary	571.30 FL	*- FL
32	1		*LH FRONT KNUCKLE ARM BEARING	Damaged	205.40 FL	*205.40 FL
33	1		*STEERING RACK & PINION	Not Necessary	1,621.50 FL	*- FL
34	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	2		*FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*30.00 FS
36	1		*FRONT FENDER TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
37	1		*FRONT BUMPER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
38	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
39	1		*FRONT LH WHEEL RIM	Cut	1,000.00 FS	*680.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,032.90	8,503.70
- List Item Discount on L Items 25.00/25.00% (S\$)	4,688.23	1,940.93
Total Parts (S\$)	15,344.67	6,562.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR SPRAYPAINTING	New	1,000.00	400.00
2	LABOUR FOR PANEL BEATING	New	1,600.00	500.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	200.00	40.00
5	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE	New	400.00	180.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			3,430.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >