

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22009372/GPA3Q2**Date:** 12/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0006968
Claimant Vehicle No : GBJ2393B **Insured Vehicle No :** SGY4943M
 Date of Loss: 20/09/2022 Nature of Claim: TP Claim No: MPC2022D0005413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ2393B**
 Make & Model: NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A) Engine No: YD25044170B
 Reg. Date: 21/02/2019 (Man. Year: 2018) Chassis No: JN1MC2E26Z0030911
 Colour: Grey Odometer: 113229 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,983.09	4,077.99	5,905.10	59.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,010.00	1,310.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,303.09	5,087.99	7,215.10	58.64
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	12,303.09	4,050.00	8,253.09	67.08
+ GST 8.00/8.00% (S\$)	984.25	324.00	660.25	67.08
Nett Amount (S\$)	13,287.34	4,374.00	8,913.34	67.08
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,976.00		

INSPECTION

Date of Assignment: 23/09/2022
 Date Inspected: 06/10/2022 Inspected At: Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Apr 2023)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2393B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	2,398.00 FN	*2,101.00 FN
2	2		*REAR TAILGATE SIDE LOCK CATCH L/R	Not Necessary	151.60 FN	*- FN
3	2		*REAR TAILGATE HINGE L/R	Not Necessary	156.20 FN	*- FN
4	2		*REAR TAILGATE DAMPER L/R	Not Necessary	630.20 FN	*- FN
5	1		*REAR TAILGATE WEATHERSTRIP	Crumpled	184.81 FN	*184.81 FN
6	1		*REAR TAILGATE MECHANISM LOCK	Jammed	371.50 FN	*287.00 FN
7	1		*REAR TAILGATE NISSAN LOGO	Necessary	94.00 FN	*94.00 FN
8	1		*REAR TAILGATE NV350 EMBLEM	Necessary	135.00 FN	*90.00 FN
9	1		*REAR TAILGATE URVAN EMBLEM	Necessary	98.40 FN	*98.40 FN
10	1		*REAR TAILGATE LOCK HOOK	Not Necessary	86.40 FN	*- FN
11	1		*REAR NO PLATE LAMP	Not Necessary	123.68 FN	*- FN
12	1		*REAR NO PLATE LAMP CHROME TRIM	Not Necessary	598.30 FN	*- FN
13	1		*REAR TAILGATE HANDLE	Not Necessary	120.56 FN	*- FN
14	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	287.60 FN	*- FN
15	2		*REAR LAMP L/R	Not Necessary	748.64 FN	*- FN
16	1		*REAR BUMPER ASSY	Deformed	833.90 FN	*667.00 FN
17	6		*REAR BUMPER SIDE HOLDER L/R	Not Necessary	90.60 FN	*- FN
18	1		*REAR BUMPER INNER CENTRE BRACKET	Bent	349.60 FN	*349.60 FN
19	1		*REAR FLOOR PANEL	Repair	2,079.60 FN	*- FN
20	1		*REAR TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
21	1		*REAR END PANEL	Repair	300.00 FS	*- FS
22	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*REAR SPARE TYRE LOCK	Not Necessary	390.00 FS	*- FS
24	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
25	1		*REAR NO PLATE	Not Necessary	35.00 FS	*- FS
26	1		*REAR TAILGATE MIRROR	Broken	196.40 FN	*196.40 FN
27	1		*REAR TAILGATE MECHANISM LOCK COVER	Cracked	65.30 FN	*65.30 FN
28	1		*SPARE TYRE HANGER	Bent	108.70 FN	*108.70 FN
					Sub Total (\$\$)	10,973.99 4,502.21
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	990.90 424.22
					Total Parts (\$\$)	9,983.09 4,077.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING	New	120.00	30.00
2	TO REMOVE ,REINSTAL REAR WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REPLACE & TRANSFER REAR BOOT LID COMPONENTS	New	250.00	60.00
4	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
5	TO PUTTY AND RESPRAY PAINTING ON REAR BOOT LID ,BUMPER AND END PANEL	New	800.00	400.00
Gross Labour Cost (\$\$)			2,320.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >