

## Vehicle Damage Assessment Report for [GBJ2393B]

Estimate Created: 23/09/2022 05:36 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 24/04/2023 16:04 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | III                          | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |       |
|----------------------|----------|--------------------|-------|
| Brand                | Nissan   | Model              | NV350 |
| Engine Type          |          |                    |       |
| License Plate Number | GBJ2393B | VIN (or Chassis #) |       |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$4,050.00 WITH 5 WORKING  
DAYS

Insurlogic 4 (24/04/2023 16:04)

**Parts**

| Description                      | Number/Type | Qty | Cost    | Markup/Disc.% | Sum      |
|----------------------------------|-------------|-----|---------|---------------|----------|
| Rear tailgate                    |             | 1   | 2101.00 | -10.00 %      | 1,890.90 |
| Rear tailgate lock               |             | 1   | 287.00  | -10.00 %      | 258.30   |
| Rear tailgate lid Nissan Logo    |             | 1   | 94.00   | -10.00 %      | 84.60    |
| Rear tailgate lid NV350 emblem   |             | 1   | 90.00   | -10.00 %      | 81.00    |
| Rear tailgate lid Urvan emblem   |             | 1   | 98.40   | -10.00 %      | 88.56    |
| Rear bumper assy                 |             | 1   | 667.00  | -10.00 %      | 600.30   |
| Rear bumper inner center bracket |             | 1   | 349.60  | -10.00 %      | 314.64   |
| Rear tailgate mirror             |             | 1   | 196.40  | -10.00 %      | 176.76   |
| Rear tailgate lock cover         |             | 1   | 65.30   | -10.00 %      | 58.77    |
| Spare tyre hanger                |             | 1   | 108.70  | -10.00 %      | 97.83    |
| Rear tailgate lid weatherstrip   |             | 1   | 184.81  | -10.00 %      | 166.33   |

Parts Subtotal 3,817.99

**Materials**

| Description                      | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|----------------------------------|-------------|-----|--------|---------------|--------|
| Rear tailgate lid 70KM/H sticker |             | 1.0 | 20.00  | 0.00 %        | 20.00  |
| Reverse sensor                   |             | 1.0 | 200.00 | 0.00 %        | 200.00 |
| Windscreen sealant               |             | 1.0 | 40.00  | 0.00 %        | 40.00  |

Materials Subtotal 260.00

**Labor****Replace/RnR**

| Description                                              | Type | Cost   | Markup/Disc % | Price  |
|----------------------------------------------------------|------|--------|---------------|--------|
| To remove and check electrical wirings and lighting.     | RnR  | 30.00  | 0.00 %        | 30.00  |
| To remove and reinstall rear windscreen.                 | RnR  | 120.00 | 0.00 %        | 120.00 |
| To remove, replace and transfer rear bootlid components. | RnR  | 60.00  | 0.00 %        | 60.00  |
| Panel beating                                            | RnR  | 400.00 | 0.00 %        | 400.00 |

**Repair**

| Description    | Severity | Cost | Markup/Disc % | Price |
|----------------|----------|------|---------------|-------|
| Rear end panel | Medium   | 0.00 | 0.00 %        | 0.00  |

|                  |        |      |        |      |
|------------------|--------|------|--------|------|
| Rear floor panel | Medium | 0.00 | 0.00 % | 0.00 |
|------------------|--------|------|--------|------|

Paint

| Description    | Paint Type    | Cost   | Markup/Disc %          | Price    |
|----------------|---------------|--------|------------------------|----------|
| Spray painting | Full spray    | 400.00 | 0.00 %                 | 400.00   |
| Labor Rate     | S\$ 50 / Hour |        | General Labor Subtotal | 610.00   |
|                |               |        | Paint Labor Subtotal   | 400.00   |
|                |               |        | Labor Subtotal         | 1,010.00 |

Summary

|                |            |
|----------------|------------|
| Repair Cost    | 5,087.99   |
| Discount(20 %) | (1,017.60) |
|                | 4,070.39   |
| Excess         | (0.00)     |
| GST(0.00 %)    | 0.00       |
| Grand Subtotal | 4,070.39   |