



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: <del>000/CTI22005900/Rny3</del>	
3 ANSON ROAD #16-00		Date: <del>21/06/2022</del> 22/09/2022	
SPRINGLEAF TOWERS SINGAPORE 079909		Code: CTI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	GBC 2466L	Veh. Inspected	SGU 131L
Policy No.	DMCVSNW00081282100	Coverage (\$)	0.00
Claim No.	SNM22D204290/C02/LEEPG	Excess (\$)	0.00
Assign From	CECILIA LEE	Assign Date	<del>21/06/2022</del> 22/09/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	20/06/2022	Inspection Date	21/06/2022
Survey held at	LYE DESIGNS 10, AMK AUTOPOINT, 04-04 ANG MO KIO IND PARK 2A, SINGAPORE 568047		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail address: aasschee@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

## VEHICLE INSPECTION REPORT

To:	Chia Yong Kwang c/o Lye Designs 10, Ang Mo Kio Industrial Park 2A # 04-04, AMK Auto Point Singapore 568047	Report No	:	TP/0015/07/2022
		Date	:	05 July 2022

### REFERENCE

Requested by	:	Chia Yong Kwang	3rd Party Vehicle No.	:	GBC 2466L
Date of Request	:	22 June 2022	Owner's Vehicle No.	:	SGU 131L
Date of Accident	:	20 June 2022	Sum Insured	:	Not Available
Date Inspected	:	22 June 2022	Policy No.	:	Not Available
Inspected at	:	Lye Designs	Claim No.	:	Not Available

### PARTICULARS OF VEHICLE

Reg. No.	:	SGU 131L	Vehicle Model	:	Forester 2.0 XT CVT AWD	Air Conditioner	:	Yes
Vehicle Make	:	Subaru	Engine No.	:	FA20BB54894	Radio/Cassette	:	Yes
Original Regn Date	:	19 January 2017	Chassis No.	:	JF1SJGK85GG079692	Seat Belt	:	Yes
Lifespan Expiry Date	:	-----	Propellant	:	Petrol	Colour	:	Silver
COE Expiry Date	:	18 January 2027	Engine Capacity	:	1,998 cc.	Speedometer	:	91,656 Km

### CONDITION OF TYRES

	MAKE	SIZE	RIM	% REMAINING
Right Front	: Bridgestone	225/55 R18	Sport Rim	70%
Left Front	: Bridgestone	225/55 R18	Sport Rim	70%
Right Rear	: Bridgestone	225/55 R18	Sport Rim	70%
Left Rear	: Bridgestone	225/55 R18	Sport Rim	70%

### DESCRIPTION OF DAMAGES

NOTE: The above vehicle was SURVEYED WITHOUT PREJUDICE

The owner's vehicle sustained damages on the rear portions.

Estimated period of repairs: 12 working days

Repairer completed the repair in: 14 (Fourteen) days inclusive of Sunday and Public Holiday

Number of photographs taken at time of inspection and attached: 18 (Eighteen) + 16 (Sixteen) Follow up Survey (After Dismantling & Damaged Parts), 10 (Ten) Follow-up Survey (Before Painting & Damaged Parts) and 09 (Nine) Follow-up Survey (After Repair/Painting And Damaged Parts) only.

### SUMMARY OF REPAIR COSTS

Repairer's Estimate	\$ 17,055.06	Estimated market value of the vehicle as at 20 June 2022	\$S 80,000.00
Revised Parts	\$ 7,201.93	Total paper rebate	\$S 37,762.00
Revised Labour	\$ 3,130.00		-----
Total Revised Amount	\$ 10,331.93	Economical cost of repair	\$S 42,238.00
			-----
Adjusted Amount	\$ 10,331.93		
Less: Owner's Excess	\$ N.A.		
Total	\$ 10,331.93		
Nett Total without GST	\$ 10,331.93		

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK TEAN (HP 96623655)  
ENG TECH. / AE MIMI / AM SAE-A  
MSAAA-Accident Damage Appraiser

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SGU 131L**

Attachment to report no.: TP/0015/07/0222

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
<b>REPLACEMENT OF DAMAGED PANELS/PARTS</b>		<b>PART BY PART REPAIR</b>	<b>LESS 20%</b>
01. 1 pc rear tailgate cover	1,465.40	Dented - To replace	1,465.40
02. 1 pc rear tailgate cover windscreen glass moulding	48.60	Necessary/Damage if removed - To replace	48.60
03. 1 pc rear tailgate cover outer garnish	589.50	Dented/Craqcked - To replace	589.50
04. 1 pc rear tailgate cover outer handle	102.60	Serviceable - To reuse	0.00
05. 1 pc rear tailgate cover outer garnish rubber	29.40	Necessary/Damage if removed - To replace	29.40
06. 2 pcs rear tailgate cove router garnish side rubber @ 16.20	32.40	Necessary/Damage if removed - To replace	32.40
07. 2 pcs rear tailgate cover number plate lamps @ 121.50	243.00	Serviceable - To reuse	0.00
08. 1 pc rear tailgate cover wiper motor	375.00	Serviceable - To reuse	0.00
09. 1 pc rear tailgate cover logo	102.60	Necessary/Damage if removed - To replace	102.60
10. 1 pc rear tailgate cover 'SUBARU' emblem	68.60	Necessary/Damage if removed - To replace	68.60
11. 1 pc rear tailgate cover 'FORESTER' emblem	62.50	Necessary/Damage if removed - To replace	62.50
12. 1 pc rear tailgate 'XT' emblem	62.50	Necessary/Damage if removed - To replace	62.50
13. 1 pc rear tailgate cover 'AWD' emblem	68.60	Necessary/Damage if removed - To replace	68.60
14. 1 pc rear tailgate cover inner lock	318.00	Serviceable - To reuse	0.00
15. 1 pc rear tailgate cover lock stricker	86.80	Serviceable - To reuse	0.00
16. 1 pc rear tailgate weatherstrip	255.80	Serviceable - To reuse	0.00
17. 2 pcs rear taillamps @ 586.20	1,172.40	Grazed - To replace (LH only)	586.20
18. 2 pcs rear taillamp panels @ 105.00	566.00	Afrfected (Bent) - To repair	To repair
19. 1 pc rear bumper	897.40	Dented/Bent - To replace	897.40
20. 1 pc rear bumper tow hook cover	77.20	Bent - To replace	77.20
21. 2 pcs rear bumper reflectors @ 126.80	253.60	Serviceable - To reuse	0.00
22. 2 pcs rear bumper brackets @ 28.60	57.20	Bent - To replace	57.20
23. 2 pcs rear bumper side retainers @ 45.50	91.00	Bent - To replace	91.00
24. 1 pc rear bumper reinforcement	352.40	Bent - To replace	352.40
25. 1 pc rear end panel	660.40	Dented/Bent - To replace	660.40
26. 1 pc rear end panel top garnish	278.40	Serviceable - To reuse	0.00
27. 1 pc rear floor board	516.00	Serviceable - To reuse	0.00
28. 1 pc rear spare tyre floor panel	820.00	Buckled/Bent - To repair	To repair
29. 1 pc rear spare tyre tools sponge tray	549.20	Cracked - To replace	549.20
30. 1 pc jack holder sponge tray	439.36	Cracked - To replace	439.36
31. 1 pc exhaust centre pipe	166.20	Bent - To replace	166.20
	-----		-----
	10,808.06		6,406.66

1072  
248-70  
95  
462  
690  
35  
X NS  
452  
X NN  
298

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)  
ENG TECH/CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SGU 131L**

Attachment to report no.: TP/0015/07/0222

REPAIRER'S ESTIMATE			OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price		Conditions	S\$ Price
<b>REPLACEMENT OF DAMAGED PANELS/PARTS</b>			<b>PART BY PART REPAIR</b>	<b>LESS 20%</b>
Carried forward from page 1/3	10,808.06			6,406.66
32. 2 pcs rear exhaust silencer @ <del>804.20</del> <b>668</b>	1,788.40		Bent - To replace	<del>1,788.40</del>
33. 2 pcs exhaust silencer mounting @ <del>156.80</del> <b>66</b>	313.60		Necessary/Damage if removed - To replace	313.60
				-----
				8,508.66
				1,701.73
				-----
				6,806.93
34. 1 tube rear tailgate cover glass sealant S.Nett	50.00		Necessary/Damage if removed - To replace	50.00
35. 1 tube spare tyre floor panel sealant S.Nett	50.00		Necessary/Damage if removed - To replace	50.00
36. 1 set rear bumper clips S.Nett	95.00		Necessary/Damage if removed - To replace	95.00
37. 1 set rear bumper reverse sensor S.Nett	200.00		Faulty - To replace	200.00
	-----			-----
	<b>13,305.06</b>			<b>7,201.93</b>
	-----			-----
<b>LABOUR CHARGES</b>				
01. Labour charges - R & R rear tailgate cover windscreen glass.	120.00		Necessary	120.00
			Reason being:	
			01. To transfer rear tailgate cover windscreen glass onto new rear tailgate cover.	
02. Labour charges - R R rear tailgate cover attachments.	80.00		Necessary	50.00
			Reason being:	
			01. To transfer/renew rear tailgate cover attachments onto new rear tailgate cover.	
03. Labour charges - R & R rear seat assy, trim covering garnishes and etc.	120.00		Necessary	100.00
			Reason being:	
			01. To remove and refit rear seat assy, garnishes, trim coveing and etc. to facilitate the repair.	
	-----			-----
	320.00			270.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

**CHEE AIK THUAN** (HP. 96623655)  
ENG TECH/CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SGU 131L**

Attachment to report no.: TP/0015/07/0222

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
<b>LABOUR CHARGES</b>			
Carried forward from page 2/3	320.00		270.00
03. Labour charges - Panel beating	1,500.00	Necessary	1,250.00
		Reason being:	
		01. To remove damaged parts and attachments, jack and cut out damaged panels, straighten chassis frames where necessary, repair and reshape dented panels, renew damaged panels (refer to our recommendations), align and weld into position, renew damaged parts (refer to our recommendations) align and refit attachments.	
04. Labour charges - R & R exhaust system	100.00	Necessary	80.00
		Reason being:	
		01. To remove exhaust system, check and renew damaged parts (refer to our recommendations).	
05. Labour charges - Spray painting	1,400.00	Necessary	1,200.00
		Reason being:	
		01. To respray paint on new rear tailgate cover (inside and outside), rear end panel, both rear taillamp panels, rear tailgate compartment, rear bumper and other affected areas.	
06. Labour charges - Anti rust proofing	200.00	Necessary	100.00
		Reason being:	
		01. To apply/respray anti rust coating.	
07. Labour charges - Lighting system	30.00	Necessary	30.00
		Reason being:	
		01. To check wiring, lighting system and conduct water leak test.	
08. Labour charges - Paint protection coat (3rd party source by the owner) See Invoice attached	200.00	Necessary	200.00
	-----		-----
	<b>3,750.00</b>		<b>3,130.00</b>

900

1,000

70

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)  
ENG TECH, CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser

8 days

## J2 Professional Carcare Pte Ltd

10 Ang Mo Kio Industrial Park 2A #03-01  
Singapore 568047  
Mobile: 9889 1100 (Derek)  
Telephone: 6753 9906


Invoice Number:

Customer Number:

Date: 4/7/22  
Time:

Customer Vehicle Number: SGU 131 L  
Payment Mode: Cash/ Nets/ Credit Card

S/No.	Item Description	Unit Price	Quantity	Total Price
1	COATING FOR BUMPER	—	—	\$200/-
	AND BOOT		Amount Payable	\$200/-

  
J2 Authorised Signature

Thank you for choosing J2 as your car protection choice!  
Have a nice day ☺