

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 7619C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID (CONSISTENT)	DENTED/ BENT	1,275.23	1,275.23
1	REAR BOOT LOGO (CONSISTENT)	NECESSARY	126.60	126.60
1	REAR BOOT EMBLEM 'TOYOTA' (CONSISTENT)	NECESSARY	89.20	89.20
1	REAR BOOT EMBLEM 'HYBRID' (CONSISTENT)	NECESSARY	121.55	121.55
2	REAR BOOT LAMPS -R/L @\$534.12 (CONSISTENT)	NOT NECESSARY	1,068.24	-
1	REAR BOOT OUTER MOULDING (CONSISTENT)	NOT NECESSARY	284.43	-
1	REAR BOOT INNER LOCK (CONSISTENT)	BENT / TWISTED	609.87	609.87
1	REAR BOOT INNER TRIM (CONSISTENT)	NOT NECESSARY	441.59	-
10	REAR BOOT INNER TRIM CLIPS @\$6.50 (CONSISTENT)	NOT NECESSARY	65.00	-
1	REAR BOOT LOCK STICKER (CONSISTENT)	NOT NECESSARY	89.95	-
1	REAR BOOT W/STRIP (CONSISTENT)	TWISTED	311.42	311.42
2	REAR BOOT HINGES -R/L @\$151.60 (CONSISTENT)	NOT NECESSARY	303.20	-
2	REAR BOOT HINGES COVER @\$110.20 (CONSISTENT)	NOT NECESSARY	220.40	-
2	REAR BOOT STOPPER @\$12.60 (CONSISTENT)	NOT NECESSARY	25.20	-
1	REAR BUMPER (CONSISTENT)	DISTORTED	702.13	702.13
1	REAR BUMPER DIFUSSER (CONSISTENT)	DISTORTED	451.78	451.78
2	REAR BUMPER REFLECTOR -R/L @\$86.65 (CONSISTENT)	CRACKED	173.30	173.30
4	REAR BUMPER PDC SENSOR @\$413.71 (CONSISTENT)	SHORTED (2 PCS ONLY)	1,654.84	827.42
2	REAR BUMPER PDC SENSOR HOLDER @\$68.55 (CONSISTENT)	NECESSARY	137.10	137.10
1	REAR BUMPER PDC SENSOR WIRE HARNESS (CONSISTENT)	NOT NECESSARY	441.90	-
1	REAR BUMPER SPONGE (CONSISTENT)	TORN	180.14	180.14
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	745.89	745.89
2	REAR BUMPER SIDE RETAINERS -R/L @\$110.25 (CONSISTENT)	BENT	220.50	220.50
1	REAR END PANEL (CONSISTENT)	DENTED / BENT	978.90	978.90
1	REAR END PANEL GARNISH (CONSISTENT)	TWISTED	617.09	617.09
1	REAR EXHAUST SILENCER (CONSISTENT)	TO REPAIR SEE LABOUR	981.60	-
1	REAR EXHAUST CHROME TRIM (CONSISTENT)	BENT	241.50	241.50

Report Ref No. CC4/ASM22009381/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR EXHAUST INSULATOR (CONSISTENT)	NOT NECESSARY	181.92	-
1	REAR FLOOR BOARD (CONSISTENT)	NOT NECESSARY	565.09	-
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	991.50	-
1	REAR FLOOR PANEL UNDERCOVER (CONSISTENT)	DISTORTED / GRAZED	454.17	454.17
2	REAR TAILLAMPS -R/L @\$797.45 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	1,594.90	797.45
1	REAR SMART KEYLESS ANTENNA (CONSISTENT)	SERVICEABLE	180.95	-
	LESS 25% DISCOUNT		-4,131.77	-2,265.31
			12,395.31	6,795.93
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	45.00	45.00
1	SET REAR FLOOR PANEL UNDERCOVER CLIP (SN) (CONSISTENT)	NECESSARY	45.00	45.00
1	REAR REVERSE CAMERA (SN) (CONSISTENT)	NOT NECESSARY	550.00	-
			640.00	90.00
	<u>LABOUR</u>			
	TO CHECK REAR WIRING.		80.00	20.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR .		120.00	80.00
	TO REMOVE & REPLACE EXHAUST SYSTEMS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS .		80.00	50.00
	TO TUFF KOTE.		80.00	60.00
	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS.		1,200.00	1,000.00
	TO PANEL BEAT ,CUT ,WELD , REMOVE & REPLACE DAMAGED PARTS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER AND REAR FLOOR PANEL .		1,200.00	800.00
			2,860.00	2,010.00
	GRAND TOTAL		15,895.31	8,895.93



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		7,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22009381/Upa3q2

CHUA KANG SENG

Licensed Appraiser