

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS22009384/KVY3Q2**Date:** 15/05/2023**REFERENCE**

Insured/Claimant: MANDAI LINK LOGISTICS PTE LTD Policy No: SPCM1000000913  
Date of Loss: 11/09/2022 Nature of Claim: OD Claim No: 202222006681SL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **YQ3990L**  
Make & Model: MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M) Engine No: 4P10D82592  
Reg. Date: 27/05/2021 (Man. Year: 2020) Chassis No: FEB71EA30141  
Colour: White Odometer: 40736 km  
Engine Capacity: 2998 cc  
Market Value/New Car Price: S\$92,000.00  
Sum Insured (\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/75 R17.50 Rear Tyre Size: 215/75 R17.50 (D)  
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9/9 mm  
Front Right Side: Dunlop 0 mm Rear Right Side: Dunlop 9/9 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                | 7,250.10          | 6,375.60          | 874.50            | 12.06         |
| Miscellaneous Items                  | 20.00             | 20.00             | 0.00              | 0.00          |
| Labour                               | 2,280.00          | 1,950.00          | 330.00            | 14.47         |
| Paintwork Labour                     | 0.00              | 0.00              | 0.00              |               |
| Towing                               | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b> | <b>9,550.10</b>   | <b>8,345.60</b>   | <b>1,204.50</b>   | <b>12.61</b>  |
| <b>- Excess (\$\$)</b>               | 0.00              | 900.00            | -900.00           |               |
| <b>(\$\$)</b>                        | 9,550.10          | 7,445.60          | 2,104.50          | 22.04         |
| <b>+ GST 7.00/8.00% (\$\$)</b>       | 668.51            | 595.65            | 72.86             | 10.90         |
| <b>Nett Amount (\$\$)</b>            | <b>10,218.61</b>  | <b>8,041.25</b>   | <b>2,177.36</b>   | <b>21.31</b>  |

**INSPECTION**

Date of Assignment: 23/09/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
Date Inspected: 23/09/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Estimated Period of Repair: 7.0 days Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                                  |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 15 May 2023)                                                                                                                                             |                                                                                  |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | mitsubishi canter 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                                |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for YQ3990L)                                                                                                                                     |                                                                                  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                                  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                                  |

### Recommended Parts

| No.                     | Qty | Part No. | Particulars                                                | Condition       | Repairer's | Amount      |
|-------------------------|-----|----------|------------------------------------------------------------|-----------------|------------|-------------|
| 1                       | 1   |          | <b>*1 PC FRT BUMPER</b><br>(WCP)                           | Bent            | 490.00 F   | *490.00 F   |
| 2                       | 1   |          | <b>*1 PC FRT BUMPER LH SIDE PAD</b><br>(WCP)               | Missing         | 180.00 F   | *180.00 F   |
| 3                       | 1   |          | <b>*1 PC FRT BUMPER LH BRACKET</b><br>(WCP)                | Bent            | 98.00 F    | *98.00 F    |
| 4                       | 1   |          | <b>*1 PC FRT BUMPER LH STAY</b><br>(WCP)                   | Bent            | 85.00 F    | *85.00 F    |
| 5                       | 1   |          | <b>*1 PC FRT BUMPER RH BRACKET</b><br>(WCP)                | Bent            | 98.00 F    | *98.00 F    |
| 6                       | 1   |          | <b>*1 PC FRT GRILLE</b><br>(WCP)                           | Cracked         | 550.00 F   | *550.00 F   |
| 7                       | 1   |          | <b>*1 SET FRT GRILLE CLIP</b><br>(WCP)                     | Necessary       | 24.00 F    | *24.00 F    |
| 8                       | 1   |          | <b>*1 PC LH SIGNAL LAMP</b><br>(WCP)                       | Broken          | 150.00 F   | *150.00 F   |
| 9                       | 1   |          | <b>*1 PC LH HEADLAMP</b><br>(WCP)                          | Serviceable     | 280.00 F   | *- F        |
| 10                      | 1   |          | <b>*1 PC FRT LH CORNAL GARNISH</b><br>(WCP)                | Cracked         | 120.00 F   | *270.00 F   |
| 11                      | 1   |          | <b>*1 PC FRT PANEL</b><br>(WCP)                            | Bent            | 520.00 F   | *520.00 F   |
| 12                      | 1   |          | <b>*1 PC FRT WIPER GARNISH</b><br>(WCP)                    | Warped          | 195.00 F   | *195.00 F   |
| 13                      | 1   |          | <b>*1 PC FRT WINDSCREEN RUBBER</b><br>(WCP)                | Cut             | 200.00 F   | *200.00 F   |
| 14                      | 1   |          | <b>*1 PC FRT LH SIDE MIRROR ROUND</b><br>(WCP)             | Missing         | 45.00 F    | *45.00 F    |
| 15                      | 1   |          | <b>*1 PC FRT LH SIDE MIRROR SQUARE BACK COVER</b><br>(WCP) | Missing         | 28.00 F    | *28.00 F    |
| 16                      | 1   |          | <b>*1 PC AIRCON EVAPORATOR</b><br>(WCP)                    | Housing Cracked | 1,650.00 F | *1,600.00 F |
| 17                      | 1   |          | <b>*1 PC CABIN FRT LH MOUNTING</b><br>(WCP)                | Distorted       | 395.00 F   | *395.00 F   |
| 18                      | 1   |          | <b>*1 PC CABIN FRT MOUNTIN CROSS BAR</b><br>(WCP)          | Bent            | 380.00 F   | *380.00 F   |
| 19                      | 1   |          | <b>*1 SET AIRCON HEATER PIPE</b><br>(WCP)                  | Serviceable     | 160.00 F   | *- F        |
| 20                      | 1   |          | <b>*1 PC HORN</b><br>(WCP)                                 | Dented          | 55.00 F    | *85.00 F    |
| 21                      | 1   |          | <b>*1 PC AIRCON GAS DISCHARGE HOSE</b><br>(WCP)            | Serviceable     | 150.00 F   | *- F        |
| 22                      | 1   |          | <b>*1 PC AIRCON GAS RECEIVER HOSE</b><br>(WCP)             | Serviceable     | 165.00 F   | *- F        |
| 23                      | 1   |          | <b>*1 PC BRAKE OIL PIPE</b><br>(WCP)                       | Serviceable     | 170.00 F   | *- F        |
| <b>Supplementary #1</b> |     |          |                                                            |                 |            |             |
| 24                      | 1   |          | <b>*1 PC LH HEADLAMP LOWER RUBBER</b><br>(WCP)             | Distorted       | 8.00 F     | *8.00 F     |
| 25                      | 1   |          | <b>*1 PC AIRCON GAS PIPING NO. 3</b><br>(WCP)              | Dented          | 260.00 F   | *260.00 F   |
| 26                      | 1   |          | <b>*1 PC CABIN FRT LH MOUNTING CUSHION</b><br>(WCP)        | Distorted       | 120.00 F   | *120.00 F   |
| 27                      | 1   |          | <b>*1 PC CABIN RH HINGE BUSHING</b><br>(WCP)               | Necessary       | 15.00 F    | *15.00 F    |

Report was unsubmitted during this print-out.

5/15/23, 11:34 AM

Adjuster Report

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's                               | Amount   |          |
|-----------------------------------------------|-----|----------|-------------|-----------|------------------------------------------|----------|----------|
| F=Franchise part.                             |     |          |             |           |                                          |          |          |
|                                               |     |          |             |           | Sub Total (S\$)                          | 6,591.00 | 5,796.00 |
|                                               |     |          |             |           | + Margin on L,N Items 10.00/10.00% (S\$) | 659.10   | 579.60   |
|                                               |     |          |             |           | Total Parts (S\$)                        | 7,250.10 | 6,375.60 |
| Report was unsubmitted during this print-out. |     |          |             |           |                                          |          |          |

Recommended Miscellaneous Items

| No                         | Qty | Particulars                            | Repairer's   | Amount       |
|----------------------------|-----|----------------------------------------|--------------|--------------|
| <b>Miscellaneous Items</b> |     |                                        |              |              |
| 1                          | 1   | 1 PC FRT NO. PLATE<br>(NPA) (REPEATED) | -            | 0.00         |
| 2                          | 1   | 1 PC FRT NO. PLATE<br>(BENT)           | 20.00        | 20.00        |
| <b>Sub Total (\$\$)</b>    |     |                                        | <b>20.00</b> | <b>20.00</b> |

Recommended Labour

| No                              | Particulars                                                                                            | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                        |          |                 |                 |
| 1                               | 1) TO REMOVE AND REFIX FRT WINDSCREEN GLASS                                                            | New      | 100.00          | 100.00          |
| 2                               | 2) TO REMOVE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS                                            | New      | 100.00          | 100.00          |
| 3                               | 3) TO REMOVE AND REFIX DASH BAORD, METER ASSY AND CHECK WIRING                                         | New      | 280.00          | 250.00          |
| 4                               | 4) TO PANEL BEATING INCLUDE STRAIGHTEN FRT LH WS PILLAR AND RE-ALIGN CABIN POSITION                    | New      | 1,000.00        | 800.00          |
| 5                               | 5) TO PUTTY AND RESPRAY ON FRT PANEL, FRT CORNAL PANEL, FRT GRILLE, BUMPER, BRACKET , FRT LH WS PILLAR | New      | 800.00          | 700.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                        |          | <b>2,280.00</b> | <b>1,950.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >