

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009762/EA3Q2-1**Date:** 27/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070035082
Claimant Vehicle No :	CB7359Z	Insured Vehicle No :	SJZ7799C
Date of Loss:	16/09/2021	Nature of Claim:	TP
		Claim No:	4383471116SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7359Z	Engine No:	ZD30032088
Make & Model:	NISSAN URVAN, 3.0 D (M)	Chassis No:	JN1TG4E25Z0700300
Reg. Date:	18/02/2004 (Man. Year: 2003)	Odometer:	525824 km
Colour:	White		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15C	Rear Tyre Size:	185 R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	912.00	779.70	132.30	14.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	580.00	350.00	37.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,842.00	1,359.70	482.30	26.18
+ GST 7.00/7.00% (S\$)	128.94	95.18	33.76	26.18
Nett Amount (S\$)	1,970.94	1,454.88	516.06	26.18
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,756.88		

INSPECTION

Date of Assignment:	17/09/2021		
Date Inspected:	20/09/2021	Inspected At:	Connect3 (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HOW MEI KWAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	733.80 F	*733.80 FL
2	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT LH SIDE LAMP	Broken	148.20 F	*148.20 FL
					Sub Total (\$)	912.00
					- List Item Discount on L Items 0.00/15.00% (\$)	0.00
					Total Parts (\$)	779.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	30.00	30.00
2	LABOUR CHARGES	New	600.00	250.00
3	SPRAY PAINTING	New	300.00	300.00
Gross Labour Cost (\$)			930.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >