

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009391/RQY3Q2**Date:** 28/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00205192204
<b>Claimant Vehicle No :</b>	SLQ8082D	<b>Insured Vehicle No :</b>	SKJ2722D
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206772/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLQ8082D	Engine No:	2ZR0B96587
Make & Model:	TOYOTA VOXY HYBRID, 1.8 V CVT (A)	Chassis No:	ZWR800331317
Reg. Date:	25/01/2019 (Man. Year: 2018)	Odometer:	207032 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,616.05	3,769.77	6,846.28	64.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,600.00	2,450.00	60.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,666.05</b>	<b>5,369.77</b>	<b>9,296.28</b>	<b>63.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>(S\$)</b>	14,666.05	4,300.00	10,366.05	70.68
<b>+ GST 8.00/8.00% (S\$)</b>	1,173.28	344.00	829.28	70.68
<b>Nett Amount (S\$)</b>	<b>15,839.33</b>	<b>4,644.00</b>	<b>11,195.33</b>	<b>70.68</b>

**INSPECTION**

Date of Assignment:	29/09/2022	
Date Inspected:	29/09/2022	Inspected At: 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 Repairer: My Car Consultant Pte Ltd (HQ)
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2023)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 V CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8082D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,458.00 FL	*1,812.70 FL
2	1		*TAILGATE LOCK	Not Necessary	640.00 FL	*- FL
3	1		*REAR TAILGATE EMBLEM HYBRID	Necessary	80.00 FL	*80.00 FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	896.00 FL	*- FL
5	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	98.40 FL	*98.40 FL
6	1		*REAR TAILGATE WEATHER STRIPE	Cut	212.00 FL	*212.00 FL
7	1		*REAR BUMPER	Deformed	720.00 FL	*720.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Not Necessary	318.00 FL	*- FL
9	2		*REAR BUMPER BRACKET	Bent	320.00 FL	*179.40 FL
10	1		*REAR END PANEL SEALANT	Bent	680.00 FL	*680.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	345.00 FL	*265.20 FL
12	1		*REAR SPARE TYRE COMPARTMENT PANEL	Not Necessary	1,156.00 FL	*- FL
13	1		*REAR SPARE TYRE COMPARTMENT CARPET	Cut	432.00 FL	*432.00 FL
14	1		*REAR FLOOR PANEL	Not Necessary	1,598.00 FL	*- FL
15	1		*REAR TOOLS BOX	Not Necessary	320.00 FL	*- FL
16	1		*REAR TOOLS BOX TOP COVER	Not Necessary	1,280.00 FL	*- FL
17	1		*REAR TOOLS BOX REAR TOP GARNISH	Not Necessary	272.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,396.00 FL	*- FL
19	1		*SET REAR REVERSE SENSOR	Not Working	250.00 FS	*220.00 FS
20	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*40.00 FS
21	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT }	Necessary	80.00 FS	*60.00 FS
22	1		*REAR TAILGATE WINDSCREEN GLASS INNER SEAL }	Necessary	80.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
24	1		*SET REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
25	1		*FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
26	1		*END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,921.40	4,889.70
- List Item Discount on L Items 25.00/25.00% (S\$)	3,305.35	1,119.93
Total Parts (S\$)	10,616.05	3,769.77

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL WIRING	New	100.00	0.00
2	TO REMOVE AND REFIT REVERSE SENSOR /CAMERA	New	150.00	60.00
3	REMOVE AND REFIX REAR UPHOLSTERY	New	300.00	0.00
4	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	New	150.00	60.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
6	CHECK AND RESET FAULT CODE LIGHT ON	New	300.00	100.00
7	TO RESPRAY UNDERCOATING	New	150.00	0.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	60.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
10	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>4,050.00</b>	<b>1,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >