

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/MSG22009396/UVY3E2**Date:** 17/10/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001871208
Claimant Vehicle No :	GBF2720L	Insured Vehicle No :	GBG8488M
Date of Loss:	22/09/2022	Nature of Claim:	TP
		Claim No:	285918

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2720L		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2616742
Reg. Date:	24/08/2016 (Man. Year: 2016)	Chassis No:	KDY2318024989
Colour:	Silver	Odometer:	218374 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6/6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,095.10	2,954.96	9,140.14	75.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	1,320.00	3,830.00	74.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,245.10	4,274.96	12,970.14	75.21
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	17,245.10	3,400.00	13,845.10	80.28
+ GST 7.00/7.00% (S\$)	1,207.16	238.00	969.16	80.28
Nett Amount (S\$)	18,452.26	3,638.00	14,814.26	80.28

INSPECTION

Date of Assignment:	26/09/2022	
Date Inspected:	23/09/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Oct 2022)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF2720L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,860.00 F	*1,482.50 FL
2	2		*REAR TAILGATE LOCK LATCHES	Repair	760.00 F	*- FL
3	2		*REAR TAILGATE LOCK LOWER L BRACKETS	Repair	360.00 F	*- FL
4	2		*REAR TAILGATE LOCK LOWER L BRACKET RUBBERS	Not Necessary	240.00 F	*- FL
5	1		*REAR TAILGATE DYNA STICKER	Necessary	80.00 F	*58.60 FL
6	1		*TAILLAMPS	N/S Cracked	900.00 F	*245.10 FL
7	1		*TAILLAMP HOUSING PANELS	N/S Bent	360.00 F	*166.00 FL
8	1		*REAR LICENCE PLATE BRACKET	Bent	345.00 F	*110.65 FL
9	1		*REAR EXHAUST	Not Necessary	1,250.00 F	*- FL
10	1		*REAR EXHAUST MOUNTING	Not Necessary	85.00 F	*- FL
11	1		*REAR LOWER MEMBER	Bent	685.10 F	*485.10 FL
12	1		*REAR CROSS MEMBER	Repair	680.00 F	*- FL
13	1		*DROPSIDE GATE PANEL N/S	Repair	2,290.00 F	*- FL
14	1		*REAR TAILGATE INNER ALUMINIUM PLATE	Bent / Dented	900.00 FS	*480.00 FS
15	1		*SET REAR TAILGATE 70KM/H & 13 PAX STICKER	Necessary	50.00 FS	*20.00 FS
16	1		*SET REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
17	1		*REAR LICENCE PLATE	Bent	50.00 FS	*14.00 FS
18	1		*SET REAR ALUMINIUM PLATE RIVET	Necessary	100.00 FS	*30.00 FS
19	1		*SET REAR LOWER STEP BAR	Bent	600.00 FS	*300.00 FS
20	1		*REAR STEP BRACKET	Repair	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,095.10	3,591.95
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	636.99
Total Parts (\$)	12,095.10	2,954.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	50.00
3	TO DISMANTLE & REPLACED REAR CARGO DECK	New	800.00	0.00
4	TO STRAIGHTEN & REALIGN CHASSIS	New	1,000.00	0.00
5	TO SPRAY RUST PROOFING	New	200.00	50.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			5,150.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >