



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2049G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,627.59	1,627.59
	LESS 25% DISCOUNT		-406.90	-406.90
			1,220.69	1,220.69
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT RIGHT ULTRASONIC SENSOR & SENSOR RETAINER, RESET REVERSE SENSOR LIGHT. CHECK WIRING.		60.00	30.00
	TO REMOVE & REPLACE REAR BUMPER. ALIGN & ADJUST REAR BUMPER AND TAIL GATE.		250.00	200.00
	TO PUTTY, RESPRAY PAINTING REAR BUMPER & ULTRASONIC SENSOR RETAINER IN PEARL WHITE. TO POLISH.		350.00	230.00
			660.00	460.00
GRAND TOTAL			1,910.69	1,710.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CS/SMR22009398/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.