

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INSI	PECTION REP	ORI		
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22009402/Evy3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date:	03/10/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 9070H	Veh. Inspected		SLV 1550P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC00/026221	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		23/09/2022	
2.		Vehicle Parti	culars & Condit	ion		
	Make & Model	TOYOTA SIENTA	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	NHP1707098587	Colour		BLACK	
	Odometer	346194 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.		Conditions of Tyres				
		Size	Make		Balance	
	R/H Front Tyre	185/55 R15	ARIVO		4 mm	
	L/H Front Tyre	185/55 R15	ARIVO		4 mm	
	R/H Rear Tyre	185/55 R15	ARIVO		4 mm	
	L/H Rear Tyre	185/55 R15	ARIVO		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	30/08/2022	Inspect Date / 1	Γime	26/09/2022 (04:57 PM)	
	Survey held at AF & CARS PTE LTD 48 TOH GUAN ROAD EAST, #01-121, ENTERPRISE HUB, SINGAPORE 6					
					SINGAPORE 608586	
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22009402/Evy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

,

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser