

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--|-----------------|-----------------------|--|
| | MS FIRST CAPITA | L INSURANCE LTD | Ref: | CS/FCI22009405/Gqy3e2 | |
| | 16 RAFFLES QUAY #42-01 HONG LEO SINGAPORE 04858 | NG BUILDING | Date: | 08/02/2023 | |
| | | | Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SBS 6535K | Veh. Inspected | SLZ 8811U | |
| | Policy No. | D-19094111MFB | Coverage (\$) | 0.00 | |
| | Claim No. | D22002920MFBP | Excess (\$) | 0.00 | |
| | Assign From | CAROLINE CABRERA | Assign Date | 23/09/2022 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | JEEP WRANGLER UNLIMITED SAHARA 3.6 | c.c | 3604 | |
| | Engine No. | HIDDEN | Year of Reg. | 2012 | |
| | Chassis No. | 1C4BJWLG3CL189778 | Colour | WHITE | |
| | Odometer | 176891 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | NIL | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 315/75 R16 | YOKOHAMA | 6 mm | |
| | L/H Front Tyre | 315/75 R16 | YOKOHAMA | 6 mm | |
| | R/H Rear Tyre | 315/75 R16 | YOKOHAMA | 6 mm | |
| | L/H Rear Tyre | 315/75 R16 | YOKOHAMA | 6 mm | |
| 4. | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 14/09/2022 | Inspection Date | 26/09/2022 | |
| | Survey held at | REVO PERFORMANCE | | | |
| | | NO 1 KAKI BUKIT AVENUE 6 #02-51 AUTOBAY @KAKI BUKI SINGAPORE 417883. | Т | | |
| 5a. | Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |