

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009409/UPA3Q2
Date: 20/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001674581
Claimant Vehicle No :	SMK8394Z	Insured Vehicle No :	SMS2682P
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	202222006834

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK8394Z	Engine No:	32755476B38A15A
Make & Model:	BMW 216I, 1.5 ACTIVE TOURER (A)	Chassis No:	WBA2X92010VD11476
Reg. Date:	26/04/2019 (Man. Year: 2018)	Odometer:	70602 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,696.40	1,032.16	664.24	39.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	440.00	560.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,696.40	1,472.16	1,224.24	45.40
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,696.40	1,100.00	1,596.40	59.20
+ GST 7.00/7.00% (S\$)	188.75	77.00	111.75	59.21
Nett Amount (S\$)	2,885.15	1,177.00	1,708.15	59.20
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,379.00		

INSPECTION

Date of Assignment:	23/09/2022	
Date Inspected:	31/10/2022 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01- 2008/2010/2012 Singapore 489977
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts: 143	BMW 216I 1.5 ACTIVE TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8394Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,050.55 F	*1,050.55 FL
2	1		*REAR BUMPER CENTER MOULDING	Cracked	96.30 F	*96.30 FL
3	1		*REVERSE SENSOR	Not Necessary	386.00 F	*- FL
4	1		*REAR BUMPER LOWER INNER COVER GARNISH RH	Not Necessary	163.55 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,696.40	1,146.85
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	114.69
Total Parts (S\$)	1,696.40	1,032.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	400.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	400.00	200.00
3	ANTI-RUST COATING	New	50.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	40.00
			Gross Labour Cost (\$\$)	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >