

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009410/AVY3Q2
Date: 16/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNW00023622200	
Claimant Vehicle No : SKX7529P	Insured Vehicle No : SND1806Z	
Date of Loss: 19/09/2022	Nature of Claim: TP	Claim No: SNM22D206776/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX7529P		
Make & Model:	BMW 535i, 3.0 L D/AB 2WD 4DR GAS/D SR HUD (A)	Engine No:	11577945N55B30A
Reg. Date:	29/12/2011 (Man. Year: 2011)	Chassis No:	WBAFR72020C958316
Colour:	Black	Odometer:	126203 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,833.55	4,611.00	15,222.55	76.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	1,050.00	4,130.00	79.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,013.55	5,661.00	19,352.55	77.37
Approved Total (Overridden) (\$\$)		4,500.00		
	25,013.55	4,500.00	20,513.55	82.01
+ GST 7.00/7.00% (\$\$)	1,750.95	315.00	1,435.95	82.01
Nett Amount (\$\$)	26,764.50	4,815.00	21,949.50	82.01

INSPECTION

Date of Assignment:	26/09/2022	
Date Inspected:	26/09/2022	Inspected At: Juzz Performance Ptd Ltd (HQ) 8 KAKI BUKIT AVENUE 4 #03-51/52 PREMIER @ KAKI BUKIT SINGAPORE 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2022)

Parts: 143 BMW 535I 3.0 L D/AB 2WD 4DR GAS/D SR HUD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX7529P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LEFT CONTROL ARM	Bent	490.00 F	*490.00 FL
2	1		*FRONT LEFT LOWER ARM	Bent	490.00 F	*490.00 FL
3	1		*FRONT LEFT TOP U ARM	Bent	530.00 F	*530.00 FL
4	1		*FRONT LEFT KNUCKLE	Not Necessary	950.00 F	*- FL
5	1		*FRONT LEFT WHEEL BEARING	Damaged	290.00 F	*290.00 FL
6	1		*FRONT LEFT ST-XA COILOVER	Not Necessary	720.00 F	*- FL
7	1		*FRONT LEFT ABSORBER MOUNTING & STOPPER	Not Necessary	210.00 F	*- FL
8	1		*FRONT LEFT BRAKE CALIPER	Not Necessary	800.00 F	*- FL
9	1		*LEFT SIDE STEERING COVER	Not Necessary	70.00 F	*- FL
10	1		*FRONT LEFT BRAKE DISC	Not Necessary	190.00 F	*- FL
11	1		*STEERING RACK	Not Necessary	6,800.00 F	*- FL
12	1		*FRONT ANTI-ROLL BAR WITH ADJUSTABLE STABILISER LINK	Not Necessary	1,240.00 F	*- FL
13	1		*UNDERCARRIAGE FRONT SPLASH GUARD	Not Necessary	180.00 F	*- FL
14	1		*FRONT BUMPER CARBON FIBRE LIP	Not Necessary	1,280.00 F	*- FL
15	1		*MICHELIN PILOT SPORT 45 TYRE 255/35/20	Not Necessary	350.00 F	*- FL
16	1		*SET 225/35/20 & 285/30/20 MICHELIN RIMS	Bent	3,663.55 FS	*1,400.00 FS
17	1		*LH FRONT HEADLIGHT	Cracked	1,580.00 F	*1,580.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,833.55	4,780.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	169.00
Total Parts (\$\$)	19,833.55	4,611.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	90.00	80.00
2	LABOUR TO REPLACE-CONTROL ARM,LOWER ARM,U ARM,KNUCKLE, WHEEL BEARING,BRAKE CALIPER,BRAKE DISC	New	320.00	220.00
3	LABOUR TO REPLACE SHOCK ABSORBER	New	90.00	0.00
4	LABOUR TO REPLACE STEERING RACK	New	250.00	0.00
5	PANEL BEATING ,REMOVAL & REPLACING PARTS	New	1,600.00	350.00
6	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	250.00
7	TUFF COAT	New	200.00	0.00
8	LABOUR TO REMOVE & REFIT FRONT UNDERCARRIAGE	New	550.00	0.00
9	LABOUR TO REMOVE & REFIX AIRCON CONDENSOR & REFILL AIRCON GAS	New	200.00	0.00
10	LABOUR TO REMOVE & REFIX RADIATOR & CONDUCT PRESSURE TEST	New	200.00	0.00
11	LABOUR TO TRANSFER HEADLIGHT CONTROL UNITS AND CODING	New	280.00	150.00
Gross Labour Cost (\$\$)			5,180.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >