

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009411/AQY3E2**Date:** 26/07/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00008132201

**Claimant Vehicle
No :** SJH8666R**Insured Vehicle
No :** SMJ1955G

Date of Loss: 20/09/2022

Nature of Claim: TP

Claim
No: SNM22D206786/C02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJH8666R**

Make & Model: OPEL ASTRA ST, 1.0 AT (A)

Engine No: B1170257HRXX0253

Reg. Date: 19/06/2017 (Man. Year: 2017)

Chassis No: W0LBE8EA6H8057616

Colour: Blue

Odometer: 87980 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,413.00	5,389.20	9,023.80	62.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	800.00	2,100.00	72.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,313.00	6,189.20	11,123.80	64.25
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	17,313.00	4,900.00	12,413.00	71.70
+ GST 8.00/8.00% (S\$)	1,385.04	392.00	993.04	71.70
Nett Amount (S\$)	18,698.04	5,292.00	13,406.04	71.70

INSPECTION

Date of Assignment: 02/10/2022

Date Inspected: 26/09/2022 Inspected At:

H S Automotives PTE LTD (HQ)
Blk 2 Kaki Bukit Avenue 2 #01-15 Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jul 2023)	
Parts:	N/A	OPEL ASTRA ST 1.0 AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH8666R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,600.00 F	*1,650.00 FL
2	2		*LH FRONT BUMPER RETAINER	Necessary	260.00 F	*85.00 FL
3	1		*FRONT BUMPER CLIP	Necessary	105.00 F	*30.00 FL
4	2		*FRONT PARKING SENSOR	Damaged	790.00 F	*265.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	1,100.00 F	*780.00 FL
6	1		*FRONT BUMPER GRILLE	Cracked	980.00 F	*408.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	425.00 F	*- FL
8	1		*LH FRONT FOG LAMP GARNISH	Cracked	125.00 F	*125.00 FL
9	1		*LH FRONT HEAD LAMP	Cracked	2,750.00 F	*2,410.00 FL
10	1		*LH FRONT HEAD LAMP LOWER BRACKET	Not Necessary	75.00 F	*- FL
11	1		*FRONT SUPPORT PANEL	Not Necessary	995.00 F	*- FL
12	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	248.00 F	*- FL
13	1		*FRONT SUPPORT PANEL GARNISH CLIP	Necessary	85.00 F	*20.00 FL
14	1		*FRONT AIR COND CONDENSOR	Not Necessary	1,222.00 F	*- FL
15	1		*FRONT RADIATOR ASSY	Not Necessary	1,424.00 F	*- FL
16	1		*LH FRONT FENDER	Not Necessary	682.00 F	*- FL
17	1		*LH FRONT FENDER INNER SHIELD	Not Necessary	192.00 F	*- FL
18	1		*LH FRONT FENDER INNER SHIELD CLIP	Not Necessary	30.00 F	*- FL
19	1		*FRONT BUMPER SPONGE	Cracked	325.00 F	*215.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	14,413.00	5,988.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	598.80
Total Parts (\$)	14,413.00	5,389.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,200.00	400.00
2	SPRAY PAINT	New	1,200.00	350.00
3	INSTALL PARKING SENSOR / WIRING	New	180.00	50.00
4	RADIATOR COOLANT	New	100.00	0.00
5	AIR CON GAS	New	100.00	0.00
6	RUST PROOF	New	120.00	0.00
Gross Labour Cost (\$\$)			2,900.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >