

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22009412/UQY3Q2**Date:** 30/11/2022**REFERENCE**

Insured/Claimant:	MTCY TRADING	Policy No:	DMCG22002171	
Date of Loss:	21/09/2022	Nature of Claim:	OD	Claim No: CDMCG22001969

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL7016Y		
Make & Model:	TOYOTA HIACE, 2.0 DX (A)	Engine No:	1TR2372218
Reg. Date:	04/02/2022 (Man. Year: 2021)	Chassis No:	TRH2000345634
Colour:	Silver	Odometer:	22734 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,301.17	4,887.27	5,413.90	52.56
Miscellaneous Items	80.00	0.00	80.00	100.00
Labour	2,440.00	1,420.00	1,020.00	41.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,821.17	6,307.27	6,513.90	50.81
- Excess (\$\$)	0.00	500.00	-500.00	
(\$\$)	12,821.17	5,807.27	7,013.90	54.71
+ GST 7.00/7.00% (\$\$)	897.48	406.51	490.97	54.71
Nett Amount (\$\$)	13,718.65	6,213.78	7,504.87	54.71

INSPECTION

Date of Assignment:	23/09/2022 Present Location:	Automobile Integrated Management Pte Ltd (HQ) Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Date Inspected:	26/09/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2022)
Parts:	213	TOYOTA HIACE 2.0 DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL7016Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet (WCP)	Badly Dented	300.00 F	*300.00 F
2	1		*Front bonnet hinges x 2pcs (WCP)	N/S Bent / O/S Repair	130.00 F	*50.00 F
3	1		*Front bonnet logo (WCP)	Necessary	55.00 F	*55.00 F
4	1		*Front bonnet inner lock (WCP)	Twisted	110.00 F	*110.00 F
5	1		*Front corner panel (N/S)(WCP)	Dented	85.00 F	*85.00 F
6	1		*Front corner panel mirror (WCP)	Repair	110.00 F	*- F
7	1		*Front Bumper (WCP)	Distorted	250.00 F	*250.00 F
8	1		*Front Foglamp x 2pcs (WCP)	Not fitted	451.80 F	*- F
9	1		*Front foglamp covers x 2pcs (WCP)	Serviceable	197.20 F	*- F
10	1		*Front Bumper grille clips (1SET)(WCP)	Not Necessary	30.00 F	*- F
11	1		*Front Bumper lower grille (WCP)	Distorted	185.70 F	*185.70 F
12	1		*Front Bumper Side Retainers (WCP)	N/S Cracked	150.00 F	*75.00 F
13	1		*Front Bumper wirehardness bracket x 2pcs (WCP)	Not Necessary	210.00 F	*- F
14	1		*Front Bumper Reinforcement (WCP)	Dented	185.00 F	*185.00 F
15	1		*Front Bumper Clips (1SET)(WCP)	Necessary	50.00 F	*30.00 F
16	1		*Front Bumper Top Beam (WCP)	Bent	145.00 F	*145.00 F
17	1		*Front Bumper Reinforcement Side Bracket x 2pcs (WCP)	Repair	130.00 F	*- F
18	1		*Front Bumper Lower Side cover x 2pcs (WCP)	Not Necessary	140.00 F	*- F
19	1		*Headlamps x 2pcs (WCP)	Cracked	760.00 F	*760.00 F
20	1		*Headlamps clips x 2pcs (2SET)(WCP)	Not Necessary	60.00 F	*- F
21	1		*Air Con Condenser (WCP)	Bent / Punctured	550.00 F	*550.00 F
22	1		*Condenser Air Con Pipe (WCP)	Not Necessary	95.00 F	*- F
23	1		*Condenser Suction Pipe (WCP)	Not Necessary	85.00 F	*- F
24	1		*Condenser Discharge Pipe (WCP)	Not Necessary	90.00 F	*- F
25	1		*Radiator expansion tank (WCP)	Not Necessary	180.00 F	*- F
26	1		*Front grille base (WCP) }	Cracked	380.00 F	*380.00 F
27	1		*Front grille top (WCP) }		220.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*Front grille lower (FRONT GRILLE INNER INSTEAD OF FRONT GRILLE LOWER) (WCP)	Cracked	285.00 F	*380.00 F
29	1		*Front grille clips (1SET)(WCP)	Not Necessary	30.00 F	*- F
30	1		*Front top support panel (WCP)	Bent	180.00 F	*180.00 F
31	1		*Front lower support panel (WCP)	Repair	150.00 F	*- F
32	1		*Brake booster pump (WCP)	Not Necessary	680.00 F	*- F
33	1		*Brake master pump (WCP)	Not Necessary	670.00 F	*- F
34	1		*Front washer tank (WCP)	Deformed	95.00 F	*95.00 F
35	1		*Front wiper garnish (WCP)	Not Necessary	200.00 F	*- F
36	1		*Front wiper garnish rubber seal (WCP)	Not Necessary	55.00 F	*- F
37	1		*Radiator (WCP)	Punctured	650.00 F	*550.00 F
38	1		*Radiator brace panel (BRACE PANEL INSTEAD OF RADIATOR BRACE PANEL)(WCP)	Bent	80.00 F	*50.00 F
39	1		*Turbo intercooler (WCP)	Not Necessary	720.00 F	*- F
40	1		*Turbo intercooler top cover (WCP)	Not Necessary	95.00 F	*- F
41	1		*Turbo intercooler rubber seal (WCP)	Not Necessary	55.00 F	*- F
42	1		*Turbo intercooler guide (WCP)	Not Necessary	85.00 F	*- F
43	1		*SET FRONT NUMBE PLATE WITH CASING	Scratched	-	*30.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	9,364.70	4,445.70
+ Margin on L,N Items 10.00/10.00% (\$\$)	936.47	441.57
Total Parts (\$\$)	10,301.17	4,887.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Radiator Coolant (NOT NECESSARY)	80.00	0.00
Sub Total (\$\$)			80.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel Beating, to weld and align damaged parts	New	1,200.00	600.00
2	Spray painting	New	1,000.00	700.00
3	Check Wiring on headlamp	New	120.00	20.00
4	Remove and install condenser /top up gas	New	120.00	100.00
Gross Labour Cost (\$\$)			2,440.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >