

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22009413/RVY3E2**Date:** 10/02/2023**REFERENCE**

Insured/Claimant: SIVAKUMAR S/O ASOKAN Policy No: MPC21P00213200
Date of Loss: 20/09/2022 Nature of Claim: OD Claim No: DMPC2200433H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB8560T**
Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: A25A5361299
Reg. Date: 12/10/2020 (Man. Year: 2020) Chassis No: JTNB23HK803065053
Colour: White Odometer: 41527 km
Engine Capacity: 2487 cc
Market Value/New Car Price: S\$147,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/40Z R19 Rear Tyre Size: 235/40Z R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,345.90	11,976.10	5,369.80	30.96
Miscellaneous Items	41.60	34.60	7.00	16.83
Labour	2,600.00	1,500.00	1,100.00	42.31
Paintwork Labour	1,050.00	1,020.00	30.00	2.86
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,037.50	14,530.70	6,506.80	30.93
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	21,037.50	13,780.70	7,256.80	34.49
+ GST 7.00/7.00% (S\$)	1,472.62	964.65	507.97	34.49
Nett Amount (S\$)	22,510.12	14,745.35	7,764.77	34.49

INSPECTION

Date of Assignment: 05/10/2022 Present Location: Convergence Automotive Pte Ltd (HQ)
Convergence Automotive Pte Ltd (HQ)
Date Inspected: 23/09/2022 Inspected At: 39 Woodlands Close, MEGA@Woodlands #01-24
Singapore 737856
Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2023)
Parts: 143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJB8560T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Buckled	440.00 F	*440.00 F
2	1		*Bonnet hinge LH (WCP)	Bent	45.00 F	*45.00 F
3	1		*Bonnet hinge RH (WCP)	Bent	45.00 F	*45.00 F
4	1		*Bonnet absorber LH (WCP)	Not Necessary	115.00 F	*- F
5	1		*Bonnet absorber RH (WCP)	Not Necessary	115.00 F	*- F
6	1		*Bumper, front (WCP)	Torn	320.00 F	*320.00 F
7	2		*Bumper retainer, front (WCP)	Cracked	110.00 F	*110.00 F
8	1		*FOG LAMP COVER LH (WCP)	Not Necessary	75.00 F	*- F
9	1		*FOG LAMP SIDE COVER (WCP)	Missing	35.00 F	*35.00 F
10	1		*FOG LAMP MOULDING TOP (WCP)	Missing	65.00 F	*65.00 F
11	1		*FOG LAMP MOULDING LOWER (WCP)	Missing	60.00 F	*60.00 F
12	1		*WHEELHOUSE LH (WCP)	Bent	410.00 F	*410.00 F
13	1		*SUPPORT SIDE PANEL LH (WCP)	Bent	180.00 F	*180.00 F
14	1		*SUPPORT TOP PANEL (WCP)	Not Necessary	195.00 F	*- F
15	1		*FENDER APRON SEAL LH (WCP)	Necessary	40.00 F	*40.00 F
16	1		*Front fender (LH) (WCP)	Buckled	265.00 F	*265.00 F
17	1		*FENDER INNER SHIELD LH (WCP)	Deformed	160.00 F	*160.00 F
18	1		*FENDER SIDE SEAL LH (WCP)	Necessary	60.00 F	*60.00 F
19	1		*FRONT FENDEER TOP COVER LH (WCP)	Cut	60.00 F	*60.00 F
20	1		*HEADLAMP LH (WCP)	Not Necessary	1,120.00 F	*- F
21	1		*FRONT BUMPER LOWE GRILLE (WCP)	Scratched	220.00 F	*220.00 F
22	1		*FRONT BUMPER LOWER GRILLE MOULDING LOWER (WCP)	Missing	85.00 F	*85.00 F
23	1		*FRONT BUMPER LOWER COVER (WCP)	Deformed	135.00 F	*135.00 F
24	1		*ENGINE UNDER COVER (WCP)	Cracked	230.00 F	*230.00 F
25	1		*FRONT DOOR LH (WCP)	Bent	720.00 F	*720.00 F
26	1		*REAR DOOR LH (WCP)	Repair	580.00 F	*- F
27	1		*HYBRID EMBLEM (WCP)	Not Necessary	35.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FRONT ABSORBER (WCP)	Not Necessary	520.00 F	*- F
29	1		*FRONT LOWER ARM (WCP)	Cracked	240.00 F	*220.00 F
30	1		*FRONT KNUCKLE ARM (WCP)	Bent	220.00 F	*220.00 F
31	1		*FRONT WHEEL BEARING WITH HUB (WCP)	Bent	200.00 F	*255.00 F
32	1		*FRONT CROSSMEMBER (WCP)	Bent	1,350.00 F	*1,350.00 F
33	1		*FRONT BUMPER SPONGE (WCP)	Cracked	75.00 F	*75.00 F
34	1		*FRONT BUMPER REINFORCMENT (WCP)	Bent	195.00 F	*195.00 F
35	1		*FRONT GRILLE (WCP)	Cracked	360.00 F	*360.00 F
36	1		*CONDENSOR (WCP)	Not Necessary	660.00 F	*- F
37	1		*RADIATOR (WCP)	Not Necessary	660.00 F	*- F
38	1		*STEERING RACK (REFER TO SUPPLEMENTARY) (WCP)	Repeated	220.00 F	*- F
39	1		*TIE ROD END (WCP)	N/S Bent	170.00 F	*85.00 F
40	1		*REAR KNUCKLE ARM LH (WCP)	Bent	400.00 F	*400.00 F
41	1		*REAR LOWER ARM LH (WCP)	Bent	190.00 F	*190.00 F
42	1		*ADDITIONAL 10% ON PARTS		1,138.00 F	*923.50 F
43	1		*CAR PLATE + CAR PLATE HODLER	Missing	35.00 F	*35.00 FS
Supplementary #2						
44	1		*FRONT SENSOR LH (WCP)	Not Working	190.00 F	*190.00 F
45	1		*ADDITIONAL 10% ON PARTS		19.00 F	*19.00 F
Supplementary #3						
46	1		*FRONT DRIVE SHAFT LH (WCP)	Bent	720.00 F	*720.00 F
47	1		*REAR WHEEL BEARING LH (WCP)	Necessary	350.00 F	*350.00 F
48	1		*REAR ABSORBER LH (WCP)	Not Necessary	90.00 F	*- F
49	1		*GEAR BOX OIL (4L) (WCP)	Necessary	46.00 F	*46.00 F
50	1		*REAR UPPER CONTROL ARM LH (WCP)	Not Necessary	220.00 F	*- F
51	1		*FRONT ABSORBER MOUNTING (WCP)	Not Necessary	80.00 F	*- F
52	1		*FRONT ABSORBER BEARING (WCP)	Not Necessary	75.00 F	*- F
53	1		*FRONT ABSORBER DUST COVER (WCP)	Not Necessary	30.00 F	*- F
54	1		*FRONT ABSORBER STOPPER (WCP)	Not Necessary	25.00 F	*- F
55	1		*FRONT ABSORBER LINK (WCP)	Not Necessary	60.00 F	*- F
56	1		*FRONT ABSORBER BUSH (WCP)	Not Necessary	18.00 F	*- F
57	1		*REAR ABSORBER STOPPER (WCP)	Not Necessary	75.00 F	*- F
58	1		*ADDITIONAL 10% ON PARTS		178.90 F	*111.60 F
Supplementary #4						
59	4		*CROSSMEMBER BUSH (WCP)	Necessary	280.00 F	*280.00 F
60	1		*DISC BRAKE DUST COVER (WCP)	Not Necessary	70.00 F	*- F
61	1		*BALL JOINT LH (WCP)	Bent	66.00 F	*66.00 F
Supplementary #5						
62	1		*STEERING RACK (AMENDED AMOUNT AS ESTIMATE PRICE KEYED WRONGLY) (WCP)	Bent	2,200.00 F	*2,200.00 F

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	17,345.90	11,976.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Supplementary #4				
1	1	ADDITIONAL 10 % ON PARTS	41.60	34.60
Sub Total (\$\$)			41.60	34.60

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAY PAINT ON AFFECTED AREA	New	1,000.00	1,000.00
2	SUNDRISE MATERIAL (5% OF SPRAY PAINT)	New	50.00	20.00
Labour Items				
3	NO OF DAYS REPAIR 10 DAYS	New	2,600.00	1,500.00
Gross Labour Cost (\$\$)			3,650.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >