

Convergence Automotive Pte Ltd (Co.Reg.No:201820703D)

39 Woodlands Close, MEGA@Woodlands #01-24

Singapore 737856

Tel: 6993 2080 Email: operations@convergence.com.sg

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC21P00213200	Date of Loss:	20/09/2022
Vehicle Reg. No.:	SJB8560T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	SIVAKUMAR S/O ASOKAN		

Make/Model:	TOYOTA CAMRY, 2.5 (A)	Vehicle Reg. Date:	12/10/2020
Vehicle Colour:	WHITE		
Engine No:	A25A5361299	Chassis No:	JTNB23HK803065053
Odometer:	41527 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: **CONVERGENCE AUTOMOTIVE PTE LTD (HQ)**

COST OF CLAIMS	Amount
Parts	12,553.00
Miscellaneous Items	0.00
Labour	2,600.00
Paintwork Labour	1,050.00
Towing	0.00
Gross Total (S\$)	16,203.00
+ GST 7.00% (S\$)	1,134.21
Nett Amount (S\$)	17,337.21

This claim is handled by: CHIA PEI FEN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Sep 2022)
 Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Convergence Automotive Pte Ltd/SJB8560T/23/09/2022 11:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>base</i>	0.00	0.00	*440.00 F
2	1		*Bonnet hinge LH <i>lt</i>	0.00	0.00	*45.00 F
3	1		*Bonnet hinge RH <i>lt</i>	0.00	0.00	*45.00 F
4	1		*Bonnet absorber LH <i>X</i>	0.00	0.00	*115.00 F
5	1		*Bonnet absorber RH <i>X</i>	0.00	0.00	*115.00 F
6	1		*Bumper, front <i>turn</i>	0.00	0.00	*320.00 F
7	2		*Bumper retainer, front <i>Crn</i>	0.00	0.00	*110.00 F
8	1		*FOG LAMP COVER LH <i>MIS</i>	0.00	0.00	*75.00 F
9	1		*FOG LAMP SIDE COVER <i>MIS</i>	0.00	0.00	*35.00 F
10	1		*FOG LAMP MOULDING TOP <i>MIS</i>	0.00	0.00	*65.00 F
11	1		*FOG LAMP MOULDING LOWER <i>MIS</i>	0.00	0.00	*60.00 F
12	1		*WHEELHOUSE LH <i>lt</i>	0.00	0.00	*410.00 F
13	1		*SUPPORT SIDE PANEL LH <i>lt</i>	0.00	0.00	*180.00 F
14	1		*SUPPORT TOP PANEL <i>X</i>	0.00	0.00	*195.00 F
15	1		*FENDER APRON SEAL LH <i>na</i>	0.00	0.00	*40.00 F
16	1		*Front fender (LH) <i>base</i>	0.00	0.00	*265.00 F
17	1		*FENDER INNER SHIELD LH <i>de</i>	0.00	0.00	*160.00 F
18	1		*FENDER SIDE SEAL LH <i>na</i>	0.00	0.00	*60.00 F
19	1		*FRONT FENDER TOP COVER LH <i>cut</i>	0.00	0.00	*60.00 F
20	1		*HEADLAMP LH <i>base</i>	0.00	0.00	*1,120.00 F
21	1		*FRONT BUMPER LOWER GRILLE <i>Sea</i>	0.00	0.00	*220.00 F
22	1		*FRONT BUMPER LOWER GRILLE MOULDING LOWER <i>MIS</i>	0.00	0.00	*85.00 F
23	1		*FRONT BUMPER LOWER COVER <i>cut</i>	0.00	0.00	*135.00 F
24	1		*ENGINE UNDER COVER <i>Crn</i>	0.00	0.00	*230.00 F
25	1		*FRONT DOOR LH <i>lt</i>	0.00	0.00	*720.00 F
26	1		*REAR DOOR LH <i>repair</i>	0.00	0.00	*580.00 F
27	1		*HYBRID EMBLEM <i>na</i>	0.00	0.00	*35.00 F
28	2		*FRONT ABSORBER <i>?</i>	0.00	0.00	*520.00 F
29	1		*FRONT LOWER ARM <i>?</i>	0.00	0.00	*240.00 F
30	1		*FRONT KNUCKLE ARM <i>?</i>	0.00	0.00	*220.00 F
31	1		*FRONT WHEEL BEARING WITH HUB <i>?</i>	0.00	0.00	*200.00 F
32	1		*FRONT CROSSMEMBER <i>?</i>	0.00	0.00	*1,350.00 F
33	1		*FRONT BUMPER SPONGE <i>Crn</i>	0.00	0.00	*75.00 F
34	1		*FRONT BUMPER REINFORCMENT <i>?</i>	0.00	0.00	*195.00 F
35	1		*FRONT GRILLE <i>Crn</i>	0.00	0.00	*360.00 F
36	1		*CONDENSOR <i>X</i>	0.00	0.00	*660.00 F
37	1		*RADIATOR <i>X</i>	0.00	0.00	*660.00 F
38	1		*STEERING RACK <i>X</i>	0.00	0.00	*220.00 F
39	2		*TIE ROD END <i>?</i>	0.00	0.00	*170.00 F
40	1		*REAR KNUCKLE ARM LH <i>?</i>	0.00	0.00	*400.00 F
41	1		*REAR LOWER ARM LH <i>?</i>	0.00	0.00	*190.00 F
42	1		*ADDITIONAL 10% ON PARTS	0.00	0.00	*1,138.00 F
43	1		*CAR PLATE + CAR PLATE HODLER <i>MIS</i>	0.00	0.00	*35.00 F

F=Franchise part.

Total Parts (S\$)

12,553.00

Convergence Automotive Pte Ltd/SJB8560T/23/09/2022 11:33. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAY PAINT ON AFFECTED AREA	New	1,000.00
2	SUNDRISE MATERIAL (5% OF SPRAY PAINT)	New	20 50.00
Labour Items			
3	NO OF DAYS REPAIR 10 DAYS	New	1500 2,600.00
Gross Labour Cost (S\$)			3,650.00

Convergence Automotive Pte Ltd/SJB8560T/23/09/2022 11:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
10 days
P/P or L/S?
23/09/22 @ 1650
EXCESS: TBA
REVERT
Resy before or after?

No. Qty Part No. Particulars

%Disc %Depr Amount

Convergence Automotive Pte Ltd/SJB8560T/23/09/2022 11:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS