



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. GBB 9984S

Qty	Description of Parts	Condition	Recommended (\$)
<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-
1	REAR LH TAILLAMP	BROKEN	248.00
1	REAR LH TAILLAMP PANEL	BENT	95.00
1	TAILGATE	DENTED	1,400.00
2	TAILGATE STICKER	NECESSARY	50.00
	LESS 10% DISCOUNT		-179.30
			1,613.70
<b><u>LABOUR</u></b>			
	LABOUR. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		400.00
	PAINT.		400.00
			800.00
<b>GRAND TOTAL</b>			<b>2,413.70</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>1,900.00</b>
---------------------------------------------------------------------------------	-----------------

Report Ref No. CS/SPF22009415/Ecy3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,900-\$2,100**

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.