

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22009423/Rqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 04/11/2022 SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 144H GBK 5695E** Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M04BFW Excess (\$) 0.00 **Assign Date LOH CYNTHIA** 26/09/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE SUPER GL 3.0 c.c Make & Model 2982 Engine No. **HIDDEN** Year of Reg. 2016 Chassis No. KDH2118007452 Colour BLUE 81466 KM **IN ORDER** Odometer Steering **IN ORDER** NIL **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 195 R15C MICHELIN 6 mm R/H Front Tyre MICHELIN L/H Front Tyre 195 R15C 6 mm R/H Rear Tyre 195 R15C **MICHELIN** 6 mm 195 R15C **MICHELIN** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. 5. **General Information Accident Date** 20/09/2022 **Inspect Date / Time** 03/10/2022 (03:55 PM) HENG YAP SENG AUTO SERVICE Survey held at 160 SIN MING DRIVE #08-13 SIN MING AUTOCITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22009423/Rgy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

3 Working Days