11/9/22, 10:03 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22009426/UNY3E2

Date: 09/11/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001958929

Claimant Vehicle No: SNC6552C Insured Vehicle No: SKZ4568K

Date of Loss: 20/09/2022 Nature of Claim: TP Claim No: 285714

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNC6552C

Make & Model: MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A) Engine No: 27091031927616

Reg. Date: 17/12/2019 (Man. Year: 2019) Chassis No: WDC1569422J672640

Colour: White Odometer: 44336 km

Engine Capacity: 1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,766.51	4,350.88	2,415.63	35.70
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,650.00	790.00	1,860.00	70.19
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,416.51	5,140.88	4,275.63	45.41
	Approved Total (Overridden) (S\$)		4,100.00		
	Nett Amount (S\$)	9,416.51	4,100.00	5,316.51	56.46

INSPECTION

Date of Assignment: 26/09/2022

Tick Hai Motor & Welding Services - Kaki Bukit (HQ)

Date Inspected: 26/09/2022 Inspected At: BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI

BUKIT

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2022)

Parts: M1-SUV MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SNC6552C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,799.00 FL	*1,366.51 FL
2	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
3	1		*FRONT BUMPER LOWER PORTION	Grazed	1,035.00 FL	*745.50 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	218.45 FL	*- FL
5	1		*FOGLAMP COVER (LH)	Repair	548.55 FL	*- FL
6	1		*HEADLAMP ASSY (LH)	Scratched / Cracked	2,044.04 FL	*2,044.04 FL
7	1		*FRONT FENDER (LH)	Repair	1,195.05 FL	*- FL
8	1		*FRONT FENDER INNER GARNISH (LH)	Torn	282.70 FL	*282.70 FL
9	1		*SET FRONT FENDER INNER GARNISH CLIP	Necessary	50.00 FL	*50.00 FL
10	1		*FRONT WHEEL ARCH PROTECTOR (LH)	Grazed	295.56 FL	*295.56 FL
F=Fra	anchise	part. L=ListIt	emDisc.	_		
				Sub Total (S\$)	7,518.35	4,834.31
			- List Item Discount	on L Items 10.00/10.00% (S\$)	751.84	483.43
				Total Parts (S\$)	6,766.51	4,350.88
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK FRONT ELECTRICAL WIRING SYSTEM & FOCUS HEADLAMP	New	150.00	20.00
2	LABOUR TO REMOVE ,CUT ,CHARGE & PANEL BEATING	New	1,300.00	320.00
3	TO PUTTY AND RESPRAY AFFECTED AREAS	New	1,200.00	450.00
	Gross Labou	r Cost (S\$)	2,650.00	790.00
	Report was unsubmitted during this pr	rint-out.		

< END OF ESTIMATES >