

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009427/ENY3Q2**Date:** 04/11/2022**REFERENCE**

Insured/Claimant: SINGAPORE ELECTRIC VEHICLES PTE. LTD.

Policy No: SPMF1000000503

Date of Loss: 24/09/2022

Nature of Claim:

OD

Claim No:

SEVAISCL2022-0023-JK

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV1072C**

Make & Model: BYD E6H, (A)

Reg. Date: 21/12/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 0 cc

Market Value/New Car Price: S\$66,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HIDDEN

Chassis No: LC0CE4DB2H1026306

Odometer: 525745 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size:

225/65 R17

Front Left Side: Sailun 4 mm

Rear Left Side:

Sailun 4 mm

Front Right Side: Sailun 4 mm

Rear Right Side:

Sailun 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,844.88	12,427.39	3,417.49	21.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,950.00	3,360.00	5,590.00	62.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,794.88	15,787.39	9,007.49	36.33
Approved Total (Overridden) (S\$)		12,650.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	22,794.88	10,650.00	12,144.88	53.28
+ GST 7.00/7.00% (S\$)	1,595.64	745.50	850.14	53.28
Nett Amount (S\$)	24,390.52	11,395.50	12,995.02	53.28

INSPECTION

Date of Assignment: 26/09/2022

Date Inspected: 26/09/2022

Inspected At:

Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2022)
Parts:	M1-MPV	BYD E6H (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1072C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER LINER (WCP)	Crushed	92.40 F	*92.40 F
2	1		*REAR RH DOOR PANEL (WCP)	Dented	1,372.00 F	*1,372.00 F
3	1		*REAR RH DOOR GLASS (WCP)	Broken	154.00 F	*154.00 F
4	1		*REAR RH DOOR GLASS RUN (WCP)	Cut	58.04 F	*58.04 F
5	1		*REAR RH DOOR LOCK (WCP)	Jammed	102.68 F	*102.68 F
6	1		*REAR RH DOOR POWER WINDOW REGULATOR MOTOR (WCP)	Bent	196.00 F	*196.00 F
7	1		*REAR RH DOOR INNER TRIM BOARD (WCP)	Crushed	434.00 F	*434.00 F
8	1		*REAR RH OUTER DOOR GLASS MOULDING (WCP)	Bent	107.96 F	*107.96 F
9	1		*REAR RH DOOR CHECK (WCP)	Not Necessary	37.34 F	*- F
10	1		*REAR RH UPPER DOOR HINGE (WCP)	Not Necessary	11.68 F	*- F
11	1		*REAR RH LOWER DOOR HINGE (WCP)	Not Necessary	11.68 F	*- F
12	1		*REAR RH DOOR WIRE HARNESS (WCP)	Not Necessary	77.56 F	*- F
13	1		*REAR RH DOOR REAR FRAME SECTION BLACK FILM (WCP)	Necessary	7.38 F	*7.38 F
14	1		*REAR RH DOOR UPPER WINDOW FRAME BLACK FILM (WCP)	Necessary	7.48 F	*7.48 F
15	1		*REAR RH DOOR FRAME WEATHERSTRIP (WCP)	Crushed	249.80 F	*249.80 F
16	1		*REAR RH DOOR REAR GLASS GUIDE CHANNEL (WCP)	Bent	25.64 F	*25.64 F
17	1		*REAR RH DOOR B PILLAR BLACK FILM (WCP)	Necessary	7.38 F	*7.38 F
18	1		*REAR RH DOOR WINDOW LOWER FRONT GLASS CHANNEL GUIDE (WCP)	Necessary	16.88 F	*16.88 F
19	1		*REAR RH DOOR INNER WEATHERSTRIP (WCP)	Cut	31.74 F	*31.74 F
20	1		*REAR RH OUTER DOOR HANDLE (WCP)	Not Necessary	62.54 F	*- F
21	1		*FRONT RH DOOR PANEL (WCP)	Dented	1,493.34 F	*1,493.34 F
22	1		*FRONT RH OUTER DOOR HANDLE (WCP)	Cut	188.94 F	*188.94 F
23	1		*FRONT RH OUTER DOOR GLASS MOULDING (WCP)	Cut	81.10 F	*81.10 F
24	1		*FRONT RH DOOR UPPER WINDOW FRAME BLACK FILM (WCP)	Necessary	8.96 F	*8.96 F
25	1		*FRONT RH DOOR B-PILLAR BLACK FILM (WCP)	Cut	8.96 F	*8.96 F
26	1		*SIDE SKIRT RH (WCP)	Broken	112.00 F	*112.00 F
27	1		*REAR RH WHEEL RIM (WCP)	Cut	373.34 F	*373.34 F
28	1		*FRONT LH FENDER PANEL (WCP)	Broken	550.68 F	*550.68 F
29	1		*SIDE SKIRT RH (WCP)	Broken	112.00 F	*112.00 F
30	1		*FRONT LH WHEEL RIM (WCP)	Cut	373.34 F	*373.34 F
31	1		*FRONT LH FENDER LINER (WCP)	Not Necessary	107.34 F	*- F
32	1		*FRONT LH DOOR PANEL (WCP)	Repair	1,493.34 F	*- F
33	1		*FRONT LH DOOR B PILLAR BLACK FILM (WCP)	Not Necessary	8.96 F	*- F
34	1		*FRONT LH DOOR UPPER WINDOW FRAME BLACK FILM (WCP)	Not Necessary	8.96 F	*- F
35	1		*SIDEWALL RH ASSY (REAR FENDER) (WCP)	Dented	4,927.12 F	*4,927.12 F
36	1		*REAR RH INNER DOOR GLASS MOULDING (WCP)	Cut	31.74 F	*31.74 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*FRONT LH BUMPER RETAINER (WCP)	Not Necessary	9.82 F	*- F
38	1		*FRONT BUMPER COVER (WCP)	Not Necessary	536.68 F	*- F
39	2		*REAR QUARTER PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
40	2		*FRONT AND REAR QUARTER GLASS PRIMER	Necessary	100.00 FS	*20.00 FS
41	3		*FRONT AND REAR QUARTER GLASS SEALANT	Not Necessary	150.00 FS	*- FS
42	1		*SET SIDE SKIRT CLIP	Necessary	50.00 FS	*20.00 FS
43	1		*SET FRONT FENDER LINER CLIP	Not Necessary	55.00 FS	*- FS
44	2		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
45	4		*SIDEWALL SEALANT	Necessary	200.00 FS	*30.00 FS
46	1		*SET FRONT AND REAR DOOR MOULDING CLIP	Necessary	55.00 FS	*30.00 FS
47	1		*REAR DOOR INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
48	1		*SET REAR FENDER LINER CLIP	Necessary	50.00 FS	*20.00 FS
49	1		*SET FRONT BUMPER CLIP	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	14,495.80	11,314.90
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,349.08	1,112.49
Total Parts (\$\$)	15,844.88	12,427.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	3,000.00	1,400.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	200.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	210.00	100.00
4	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	240.00	30.00
5	TO REFIT REAR REVERSE SENSOR	New	100.00	30.00
6	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	120.00	80.00
7	TO REMOVE AND REFIT FRONT AND REAR QUARTER GLASS TO ENABLE BODYWORK REPAIR	New	180.00	100.00
8	TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR	New	180.00	0.00
9	TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	New	220.00	100.00
10	TO VACUUM REAR DOOR GLASS SHARD AND WASH REAR SEAT	New	100.00	30.00
11	TO CHECK AND REPAIR WIRE HARNESS	New	150.00	0.00
12	TO RESPRAY REAR OUTER QUARTER PANEL	New	250.00	200.00
13	TO RESPRAY REAR INNER QUARTER PANEL	New	250.00	0.00
14	TO RESPRAY REAR DOOR PANEL	New	250.00	200.00
15	TO RESPRAY SIDE SKIRT RH	New	250.00	200.00
16	TO RESPRAY ROCKER PANEL OUTER RH	New	250.00	0.00
17	TO RESPRAY CENTER PILLAR OUTER RH	New	250.00	0.00
18	TO RESPRAY FRONT RH DOOR PANEL	New	250.00	200.00
19	TO RESPRAY REAR BUMPER	New	250.00	0.00
20	TO RESPRAY REAR BUMPER	New	250.00	0.00
21	TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE AND COVER	New	250.00	60.00
22	TO RESPRAY REAR UPPER AND LOWER DOOR HINGE	New	250.00	0.00
23	TO RESPRAY FRONT BUMPER	New	250.00	0.00
24	TO RESPRAY FRONT LH FENDER PANEL	New	250.00	200.00
25	TO RESPRAY FRONT LH DOOR PANEL	New	250.00	200.00
26	TO RESPRAY SIDE SKIRT LH	New	250.00	200.00
27	TO RESPRAY FRONT WHEEL RIM	New	250.00	0.00
28	TO RESPRAY REAR WHEEL RIM	New	250.00	0.00
Gross Labour Cost (\$\$)			8,950.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >