11/2/22, 12:14 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22009428/EQY3Q2

**Date:** 02/11/2022

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

Claimant Vehicle SBS3816U Insured Vehicle No: GBL1127A

No: SBSS6160 BISUTED NO. GBET127A

Date of Loss: 16/09/2022 Nature of Claim: TP Claim No: 2022 22006898KC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SBS3816U

Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9192459

Reg. Date: 10/07/2014 (Man. Year: 2014) Chassis No: YV3S4P920EA167584

Colour: Multi-colour Odometer: 628712 km

Engine Capacity: 9364 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,953.00	2,953.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,288.00	988.00	300.00	23.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,241.00	3,941.00	300.00	7.07
+ GST 7.00/7.00% (S\$)	296.87	275.87	21.00	7.07
Nett Amount (S\$)	4,537.87	4,216.87	321.00	7.07

Global Sum Settlement (S\$) 0.00

**INSPECTION** 

Date of Assignment: 26/09/2022

Sbs Transit Pte Ltd (ulu Pandan) (HQ)

Date Inspected: 26/09/2022 Inspected At: Ulu Pandan WS, 1 Business Park Drive, Singapore

608506.

Singapore 608506

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 01 Nov 2022)

Parts: N/A VOLVO B9TL 9.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS3816U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*OS NO 4 BODY PANEL	Dented	952.00 F	*952.00 F
2	1	*OS NO 3 BODY PANEL	Dented	858.00 F	*858.00 F
3	1	*OS LOWER BODY PILLAR	Broken	1,143.00 F	*1,143.00 F
F=Fra	anchise part.		Total Parts (S\$)	2,953.00	2,953.00
		Report was unsubmi	itted during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE /REPLACE /REPAIR DAMAGED PARTS BY WORKSHOP	<b>P</b> New	188.00	188.00
2	TO REMOVE /REPLACE /REPAIR DAMAGED PARTS BY CONTRACTOR	New	800.00	800.00
3	TO REMOVE /REPLACE /REPAIR DAMAGED ADVERTISEMENT PANEL	New	300.00	0.00
4	TOWING COST (NPA)	New	0.00	0.00
	Gross Labo	ur Cost (S\$)	1,288.00	988.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >