



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 9034P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	BENT	280.00	280.00
1	FRONT SPOILER (WCP)	BROKEN	380.00	240.00
1	FRT BUMPER TRIM CAP (WCP)	NOT NECESSARY	12.00	-
1	GRILLE (WCP)	CRACKED	220.00	220.00
1	L/FASTENING CLIP (WCP)	NECESSARY	15.00	15.00
1	LWR RADIATOR GRILLE (WCP)	DISTORTED	75.00	75.00
1	R/FASTENING CLIP (WCP)	NECESSARY	25.00	25.00
1	R/F BUMPER COVER (WCP)	MISSING	55.00	55.00
1	R/F FOG LAMP (WCP)	MTG CRACKED	195.00	195.00
1	R/F HEADLAMP (WCP)	MTG BROKEN	205.00	205.00
1	R/F UPP BUMPER BRKT (WCP)	DISTORTED	10.00	10.00
1	R/F WHEELHOUSE COVER (WCP)	TORN	52.00	52.00
1	UPPER FRONT PANEL (WCP)	CRACKED	48.00	48.00
1	MANUFACTURER BADGE (WCP) (ADDITIONAL)	NECESSARY	25.00	25.00
	COST PLUS 10%		159.70	144.50
			1,756.70	1,589.50
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	MISSING	35.00	35.00
			35.00	35.00
<u>LABOUR</u>				
	TOWING FEE.		50.00	50.00
	65.0 WU X 50.00 SGD/H.		325.00	325.00
	LABOUR COST 72.0 WU X 50.00 SGD/H.		360.00	345.00
	MATERIAL COST.		138.15	137.66
			873.15	857.66
GRAND TOTAL			2,664.85	2,482.16



RECOMMENDED COST OF REPAIRS			2,482.16
------------------------------------	--	--	-----------------

Report Ref No. CS/SGK22009429/Kcy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.