



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 4659D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LID COMP TRUNK (SN)	DENTED	543.52	543.52
1	GARNISH ASSYRR.LICENSE (SN)	BROKEN	87.07	87.07
1	EMBLEM SETRR. (SN)	NECESSARY	10.20	10.20
1	EMBLEMRR. (SN)	NECESSARY	9.52	9.52
1	FACE ASSY,RR.BUMPER (SN)	DENTED	462.90	462.90
1	REFLECTOR ASSYR.RR (SN)	NOT NECESSARY	14.40	-
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	14.40	-
1	GARNISH,RR.BUMPER LOWER (SN)	CUT	31.50	31.50
1	GARNISH,R.RR.BUMPER SIDE (SN)	CUT	6.75	6.75
1	GARNISH,L.RR BUMPER SIDE (SN)	NOT NECESSARY	6.75	-
1	BEAM COMPRR.BUMPER (SN)	BENT	142.57	142.57
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	PANEL SETRR. (SN)	DENTED	210.52	210.52
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	37.72	-
1	TAILLIGHT ASSYR. (SN)	BROKEN	226.27	226.27
1	TAILLIGHT ASSYL. (SN)	NOT NECESSARY	243.52	-
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	105.82	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	105.82	-
1	NUMBER PLATE WITH CASING (SN)	CUT	45.00	45.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	STIFFENERL.RR.PANEL SIDE (SN) (ADDITIONAL)	DENTED	23.10	23.10
1	WEATHERSTRIPTRUNK LID (SN) (ADDITIONAL)	TORN	52.50	52.50
			2,459.16	1,883.49
	<u>LABOUR</u>			
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		280.00	250.00
	REMOVE & RENEW REVERSE SENSORS - 4 PCS.		280.00	250.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		650.00	325.00
	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID.		560.00	325.00

Report Ref No. CS/UOI22009430/Evy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESET VEHICLE SMART ENTRY SYSTEM.		560.00	500.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		560.00	500.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.		5,200.00	2,600.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)		3,120.00	2,600.00
			11,210.00	7,350.00
GRAND TOTAL			13,669.16	9,233.49
RECOMMENDED COST OF REPAIRS				9,233.49

Report Ref No. CS/UOI22009430/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.