

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG22009436/ANY3Q2**Date:** 03/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900262343
Claimant Vehicle No :	SMS42A	Insured Vehicle No :	SMR3248J
Date of Loss:	13/09/2022	Nature of Claim:	TP
		Claim No:	2246689897SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS42A	Engine No:	BWA143591
Make & Model:	VOLKSWAGEN GOLF, 2.0 GTI (A)	Chassis No:	WVWZZZ1KZ7U040342
Reg. Date:	02/10/2007 (Man. Year: 2007)	Odometer:	239849 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,026.70	3,195.50	5,831.20	64.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,200.00	3,300.00	73.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,526.70	4,395.50	9,131.20	67.51
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	13,526.70	3,500.00	10,026.70	74.13

INSPECTION

Date of Assignment:	26/09/2022		BLK 1 KAKI BUKIT AVENUE 6
Date Inspected:	30/09/2022	Inspected At:	#01-08 AUTOBAY @ KAKI BUKIT
			SINGAPORE 417883
			Repairer:TSL Auto Garage
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,690.00 FL	*1,235.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH & RH	O/S Necessary	220.00 FL	*65.00 FL
3	1		*REAR BUMPER CENTER BRACKET	Not Necessary	200.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	490.00 FL	*- FL
5	1		*REAR TAIL LAMP LOWER BRACKET RH	Not Necessary	143.00 FL	*- FL
6	1		*REAR FENDER RH	Repair	1,930.00 FL	*- FL
7	1		*REAR TAIL LAMP PANEL RH	Repair	395.00 FL	*- FL
8	1		*REAR FENDER INNER SHIELD RH	Deformed	420.00 FL	*210.00 FL
9	1		*REAR FENDER INNER AIR DUCT RH	Deformed	185.00 FL	*85.00 FL
10	1		*REAR WHEEL HUB BEARING RH	Not Necessary	590.00 FL	*- FL
11	1		*REAR BUMPER LOWER SKIRTING	Deformed	1,000.00 FS	*800.00 FS
12	1		*REAR TAIL LAMP RH (SMOKE)	Cracked	790.00 FS	*400.00 FS
13	1		*REAR SPORT RIMS RH	Cut	800.00 FS	*500.00 FS
14	1		*REAR TYRE RH	Not Necessary	400.00 FS	*- FS
15	1		*REAR BUMPER LOWER SIDE SKIRTING -RH	Not Necessary	300.00 FS	*- FS
16	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*REAR BUMPER LOWER SKIRTING CLIPS	Necessary	50.00 FS	*30.00 FS
					Sub Total (S\$)	9,653.00 3,355.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	626.30 159.50
					Total Parts (S\$)	9,026.70 3,195.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT REAR FRAME MEMBERS ,TO CUT /WELD AND REMOVE AND REFIT ABOVE PARTS	New	1,600.00	400.00
2	TO PUTTY ,RESPRAY PAINTING AND POLISH REAR AFFECTED AREAS	New	1,600.00	600.00
3	TO RUST PROOF AFFECTED AREAS	New	100.00	40.00
4	TO REMOVE AND REFIT UPHOLSTERY ,SEATS ,GARNISH ,INNER TRIMMING BOARDS	New	200.00	0.00
5	TO CHECK AND RECTIFY WIRING	New	100.00	30.00
6	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	50.00
7	TO CONDUCT DIAGNOSTIC SYSTEMS AND TO CLEAR FAULTS CODE	New	200.00	0.00
8	TO REMOVE AND REFIT REAR FUEL TANK ASSY IN ORDER TO REMOVE REAR FENDER	New	200.00	0.00
9	TO REMOVE AND REFIT REAR UNDER CARRIAGE ASSY	New	300.00	0.00
10	TO CONDUCT WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			4,500.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >