



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3190Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	NOT NECESSARY	1,674.00	-
1	FRONT BUMPER SIDE HOLDER RH (CONSISTENT)	NOT NECESSARY	58.00	-
1	HEADLAMP RH (CONSISTENT)	CRACKED	3,366.00	3,366.00
1	FRONT RH FENDER (CONSISTENT)	DENTED	977.00	977.00
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	221.00	-
1	FRONT RH DOOR WING MIRROR MOUNTING (CONSISTENT)	NOT NECESSARY	1,075.00	-
1	FRONT RH DOOR WING MIRROR COVER (CONSISTENT)	CRACKED	85.00	85.00
1	FRONT RH DOOR WING MIRROR SIGNAL LAMP (CONSISTENT)	NOT NECESSARY	189.00	-
1	FRONT RH LOWER ARM (CONSISTENT)	BENT	335.00	335.00
1	FRONT RH SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	749.00	-
1	FRONT RH KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	1,208.00	-
1	FRONT RH WHEEL HUB C/W BEARING (CONSISTENT)	DAMAGED	332.00	332.00
	LESS 10% DISCOUNT		-	-509.50
			10,269.00	4,585.50
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT RH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT RH WHEEL RIM (SN) (CONSISTENT)	CUT	1,280.00	780.00
1	FRONT RH TYRE (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
			1,660.00	780.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING.		800.00	300.00
	WIRING.		100.00	30.00
	TO SPRAY TUFF COAT.		150.00	30.00
	TO DISMANTLE FRONT UNDERCARRIAGE.		350.00	120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			2,350.00	960.00
GRAND TOTAL			14,279.00	6,325.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/ASM22009441/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.