



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 6714L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR (CONSISTENT)	TWISTED/ BENT	168.00	168.00
1	HANDLE BAR END (CONSISTENT)	CUT	106.00	30.00
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	68.00	-
1	SIDE MIRROR -R/H (CONSISTENT)	NOT NECESSARY	120.00	-
1	SET FAIRING ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	680.00	-
1	FRONT FOOTREST BRACKET -R/H (CONSISTENT)	TO REPAIR SEE LABOUR	185.00	-
1	FRONT FOOTREST -R/H (CONSISTENT)	CUT	95.00	75.00
1	BRAKE PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	105.00	-
1	REAR FOOTREST -R/H (CONSISTENT)	NOT NECESSARY	90.00	-
1	REAR FOOTREST BRACKET -R/H (CONSISTENT)	NOT NECESSARY	160.00	-
1	EXHAUST ASSY (CONSISTENT)	NOT NECESSARY	685.00	-
1	EXHAUST PROTECTOR (CONSISTENT)	CUT	108.00	108.00
1	EXHAUST PROTECTOR END COVER (CONSISTENT)	CUT	88.00	60.00
1	REAR NUMBER PLATE LAMP (CONSISTENT)	NOT NECESSARY	105.00	-
1	REAR TAILLAMP (CONSISTENT)	NOT NECESSARY	220.00	-
1	REAR FENDER (CONSISTENT)	DISTORTED	165.00	165.00
1	REAR NUMBER LAMP TOP COVER (CONSISTENT)	DEFORMED	130.00	130.00
1	REAR WHEEL RIM (CONSISTENT)	NOT NECESSARY	480.00	-
1	REAR RIM SHAFT (CONSISTENT)	NOT NECESSARY	105.00	-
1	REAR RIM BEARING (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BRAKE DISC (CONSISTENT)	NOT NECESSARY	185.00	-
1	SWING ARM (CONSISTENT)	NOT NECESSARY	620.00	-
	LESS 10% DISCOUNT		-474.80	-73.60
			4,273.20	662.40
SPECIAL NETT ITEMS				
1	SET NUMBER PLATE (SN) (CONSISTENT)	REAR BENT	38.00	12.00
1	STICKER (SN) (CONSISTENT)	NOT NECESSARY	125.00	-
1	REAR BOX (SN) (CONSISTENT)	CUT	480.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
1	REAR TYRE (SN) (CONSISTENT)	NOT NECESSARY	230.00	-
			1,053.00	262.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE REAR BODY REPAIR .	NOT NECESSARY	420.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF SET FAIRING ASSY,FRONT FOOTREST BRACKET -R/H AND BRAKE PEDAL .		480.00	250.00
			980.00	250.00
GRAND TOTAL			6,306.20	1,174.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00
---	--	--	---------------

Report Ref No. CC4/ASM22009448/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.