



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 9816J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (CONSISTENT)	DISTORTED / TORN	2,260.00	1,280.00
1	FRONT BUMPER BEAM (CONSISTENT)	NOT NECESSARY	915.00	-
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	HEADLAMP N/S (CONSISTENT)	CRACKED	1,850.00	1,150.00
1	FRONT FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	885.00	-
	LESS 10% DISCOUNT		-	-248.00
			5,960.00	2,232.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S .		480.00	240.00
	TO PUTTY & SPRAY PAINTING.		680.00	400.00
			1,260.00	660.00
<b>GRAND TOTAL</b>			<b>7,220.00</b>	<b>2,892.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,300.00</b>

Report Ref No. CC4/ASM22009451/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.