

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22009458/APA3Q2**Date:** 27/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_01
Claimant Vehicle No : SJS5078A **Insured Vehicle No :** SHD2866P
 Date of Loss: 24/09/2022 Nature of Claim: TP Claim No: MFL2022D0005510

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS5078A**
 Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H283755
 Reg. Date: 21/08/2009 (Man. Year: 2009) Chassis No: KNAFW411MA5112297
 Colour: Bronze Odometer: 17125 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,529.78	1,781.84	3,747.94	67.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	830.00	730.00	46.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,089.78	2,611.84	4,477.94	63.16
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	7,089.78	2,000.00	5,089.78	71.79
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 26/09/2022
 Date Inspected: 27/09/2022 Inspected At: Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	143	KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS5078A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER O/S RETAINER	Damaged	52.00 FL	*36.00 FL
2	1		*FRONT BUMPER	Deformed	834.60 FL	*688.00 FL
3	1		*FRONT BUMPER INSULATOR	Not Necessary	131.40 FL	*- FL
4	1		*FRONT BUMPER LOWER DIFFUSER	Not Necessary	323.10 FL	*- FL
5	1		*FRONT BUMPER O/S SIGNAL LAMP	Not Necessary	221.30 FL	*- FL
6	1		*FRONT BUMPER O/S SIGNAL LAMP GARNISH	Not Necessary	55.00 FL	*- FL
7	1		*FRONT BUMPER O/S FOG LAMP	Not Necessary	252.68 FL	*- FL
8	1		*FRONT BUMPER O/S FOG LAMP GARNISH	Not Necessary	48.00 FL	*- FL
9	1		*FRONT BUMPER GRILLE (LOWER)	Not Necessary	320.50 FL	*- FL
10	1		*FRONT O/S HEAD LAMP	Cracked	3,107.70 FL	*588.00 FL
11	1		*FRONT O/S FENDER	Dented	545.60 FL	*545.60 FL
12	1		*FRONT O/S FENDER INNER TRIM	Not Necessary	130.10 FL	*- FL
13	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT O/S RIM	Cut	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,131.98	1,967.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	602.20	185.76
Total Parts (\$\$)	5,529.78	1,781.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE REAR & FRONT DAMAGED PARTS ,STRAIGHTEN & WELDING	New	800.00	400.00
2	TO SPRAY PAINTING	New	600.00	400.00
3	TO CHECK WIRING	New	60.00	30.00
4	TO RE-SEAL ANTI RUST	New	100.00	0.00
Gross Labour Cost (\$\$)			1,560.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >