

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22009459/DQY3Q2
Date: 20/02/2023

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP319989
Claimant Vehicle No : SH9126U **Insured Vehicle No :** SDF8896A
Date of Loss: 25/09/2022 Nature of Claim: TP Claim No: MPC03704/LJ

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH9126U**
Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZRS048302
Reg. Date: 15/06/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503558746
Colour: Blue Odometer: 753735 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Davanti 5 mm Rear Left Side: Davanti 5 mm
Front Right Side: Davanti 5 mm Rear Right Side: Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,706.23	6,712.98	14,993.25	69.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	1,510.00	3,310.00	68.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,526.23	8,222.98	18,303.25	69.00
Approved Total (Overridden) (S\$)		6,550.00		
(S\$)	26,526.23	6,550.00	19,976.23	75.31
+ GST 8.00/8.00% (S\$)	2,122.10	524.00	1,598.10	75.31
Nett Amount (S\$)	28,648.33	7,074.00	21,574.33	75.31

INSPECTION

Date of Assignment: 26/09/2022
Date Inspected: 27/09/2022 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644
Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2023)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SH9126U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Bent	1,303.29 FL	*1,303.29 FL
2	1		*REAR TRUNK LID LOCK	Damaged	530.79 FL	*530.79 FL
3	1		*REAR TRUNK LID LOCK COVER	Serviceable	129.80 FL	*- FL
4	1		*REAR TRUNK LID LOCK SWITCH	Not Necessary	468.90 FL	*- FL
5	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	254.40 FL	*- FL
6	1		*BOOT LID TRIMBOARD CENTRE	Not Necessary	159.60 FL	*- FL
7	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	185.00 FL	*- FL
8	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
9	1		*BOOT HANDLE	Not Necessary	31.80 FL	*- FL
10	1		*REAR TRUNK LID RUBBER	Necessary	365.20 FL	*365.20 FL
11	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Not Necessary	969.70 FL	*- FL
12	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Mtg Cracked	1,054.71 FL	*1,054.71 FL
13	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	62.14 FL	*62.14 FL
14	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	62.14 FL	*62.14 FL
15	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	81.43 FL	*81.43 FL
16	1		*THIRD BRAKE LIGHT	Not Necessary	394.70 FL	*- FL
17	1		*REAR TRUNK LID STRIKER	Not Necessary	98.70 FL	*- FL
18	2		*REAR TRUNK LID HINGE (LH/RH)	Not Necessary	379.00 FL	*- FL
19	2		*REAR TRUNK LID ABSORBER (LH/RH)	Not Necessary	575.00 FL	*- FL
20	2		*REAR TRUNK LID ABSORBER BRACKET (LH/RH)	Not Necessary	255.80 FL	*- FL
21	2		*REAR TRUNK LID STOPPER (LH/RH)	Not Necessary	169.60 FL	*- FL
22	1		*SPOILERSUB-ASSY ,REAR	Not Necessary	1,787.79 FL	*- FL
23	1		*REAR WINDSCREEN GLASS W/MOULDING	Not Necessary	1,884.32 FL	*- FL
24	1		*ROOF TOP CENTER COVER ,BLACK	Not Necessary	956.30 FL	*- FL
25	1		*ROOF TOP GARNISH SUB,LH	Not Necessary	136.80 FL	*- FL
26	1		*ROOF TOP GARNISH SUB,RH	Not Necessary	136.80 FL	*- FL
27	2		*REAR NO PLATE LAMP LH/RH	Not Necessary	327.00 FL	*- FL
28	1		*REAR BUMPER	Dented	503.04 FL	*503.04 FL
29	1		*REAR BUMPER REINFORCEMENT	Bent	378.32 FL	*378.32 FL
30	1		*REAR BUMPER LOWER COVER	Distorted	654.96 FL	*654.96 FL
31	2		*REAR BUMPER SIDE RETAINER	Serviceable	225.40 FL	*- FL
32	1		*REAR BUMPER TOWING COVER	Dislodged	82.70 FL	*82.70 FL
33	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
34	2		*REAR BUMPER SIDE CLIP	Not Necessary	50.00 FL	*- FL
35	2		*REAR BUMPER UPPER STOPPER (LH/RH)	Not Necessary	152.80 FL	*- FL
36	2		*SEAL ,REAR BUMPER SIDE ,LH/RH	Mtg Broken	296.80 FL	*296.80 FL
37	2		*REAR BUMPER UNDER SIDE COVER (LH/RH)	Serviceable	464.00 FL	*- FL
38	2		*ARM SUB-ASSY ,REAR BUMPER (LH/RH)	Not Necessary	279.20 FL	*- FL
39	1		*REAR BUMPER REVERSE SENSOR	Damaged	235.70 FL	*235.70 FL
40	2		*TAIL LAMP ASSY (UPPER)	Cracked	1,115.80 FL	*1,115.80 FL
41	2		*TAIL LAMP ASSY (LOWER)	Mtg Broken	1,140.00 FL	*1,140.00 FL
42	2		*TAIL LAMP QUARTER PANEL	Not Necessary	432.00 FL	*- FL
43	2		*TAIL LAMP SIDE COVER	Serviceable	512.00 FL	*- FL
44	1		*REAR TAILLAMP GUIDE -WHITE	Not Necessary	95.30 FL	*- FL
45	1		*REAR END PANEL	Dented	738.96 FL	*738.96 FL
46	1		*REAR END PANEL GARNISH	Not Necessary	294.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR SPARE TYRE PANEL	Not Necessary	960.80 FL	*- FL
48	1		*REAR END PANEL GARNISH COVER	Not Necessary	138.90 FL	*- FL
49	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Not Necessary	668.90 FL	*- FL
50	2		*REAR FIBER TOOL BOX TRIM (LH/RH)	Not Necessary	1,196.00 FL	*- FL
51	1		*REAR FIBER TOOL BOX CENTER	Not Necessary	186.20 FL	*- FL
52	1		*SPARE TYRE LOCK NUT	Not Necessary	88.40 FL	*- FL
53	1		*SPARE TYRE LOCK NUT BRACKET	Not Necessary	113.50 FL	*- FL
54	2		*SPARE TYRE SIDE PANEL (LH/RH)	Not Necessary	574.60 FL	*- FL
55	1		*REAR EXHAUST PIPE RH	Not Necessary	1,163.40 FL	*- FL
56	1		*REAR EXHAUST PIPE HANGER	Not Necessary	40.70 FL	*- FL
57	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	314.60 FL	*- FL
58	1		*REVERSE CAMERA ASSY	Not Necessary	380.00 FS	*- FS
59	1		*REAR TRUNK LOWER W/S MOULDING	Not Necessary	180.00 FS	*- FS
60	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
61	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
62	1		*REAR NO PLATE WITH COVER	Not Necessary	100.00 FS	*- FS
63	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
64	1		*REAR TRUNK LID COMFORT &TEL NO STICKER	Necessary	60.00 FS	*60.00 FS
65	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	26,907.29	8,869.98
- List Item Discount on L Items 20.00/25.00% (\$)	5,201.06	2,157.00
Total Parts (\$)	21,706.23	6,712.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING CHARGE	New	1,600.00	600.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	120.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE /REFIX EXHAUST PIPE	New	80.00	0.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
			Gross Labour Cost (S\$)	4,820.00
				1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >