

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22009463/KYA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900095062
<b>Claimant Vehicle No :</b>	SLP989X	<b>Insured Vehicle No :</b>	SGA1002A
Date of Loss:	24/09/2022	Nature of Claim:	TP
		Claim No:	0377802438SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLP989X</b>	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Chassis No:	LRW3F7FJ6MC282859
Reg. Date:	24/09/2021 (Man. Year: 2021)	Odometer:	19295 km
Colour:	Metallic Pearl White	Engine Capacity:	0 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	<b>Market Value/New Car Price</b>

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,243.17	4,441.79	2,801.38	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,960.00	1,170.00	37.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,373.17</b>	<b>6,401.79</b>	<b>3,971.38</b>	<b>38.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	726.12	448.13	277.99	38.28
<b>Nett Amount (S\$)</b>	<b>11,099.29</b>	<b>6,849.92</b>	<b>4,249.37</b>	<b>38.29</b>
<b>+ Loss of Use (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,551.92</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,551.91</b>		

**INSPECTION**

Date of Assignment:	27/09/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	27/09/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	6.0 days	Singapore 568047

**Adjuster:** KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cracked	1,308.41 FL	*1,308.41 FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	7.48 FL	*- FL
3	1		*FRONT BUMPER	Buckled	631.00 FL	*631.00 FL
4	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	9.35 FL	*9.35 FL
5	1		*FRONT BUMPER UPPER BRACKET RH	Serviceable	1.87 FL	*- FL
6	1		*FRONT BUMPER PARKING SENSOR	Serviceable	163.55 FL	*- FL
7	1		*FRONT BUMPER PARKING SENSOR BRACKET	Serviceable	4.67 FL	*- FL
8	1		*FRONT FENDER RH	Bent	448.60 FL	*448.60 FL
9	1		*FRONT FENDER INNER SHIELD RH	Cracked	116.82 FL	*116.82 FL
10	1		*FRONT FENDER SIDE RETAINER RH	Dented	196.26 FL	*196.26 FL
11	1		*FRONT RIM RH	Dented	505.00 FL	*505.00 FL
12	1		*FRONT RIM COVER RH	Dented / Cut	32.71 FL	*32.71 FL
13	1		*FRONT ABSORBER RH	Serviceable	429.91 FL	*- FL
14	1		*FRONT UPPER ARM RH	Distorted	121.50 FL	*121.50 FL
15	1		*FRONT LOWER ARM RH	Bent	224.30 FL	*224.30 FL
16	1		*FRONT KNUCKLE ARM RH	Bent	420.56 FL	*420.56 FL
17	1		*FRONT WHEEL BEARING HUB RH	Necessary	233.64 FL	*233.64 FL
18	1		*FRONT DOOR RH	Repair	1,009.35 FL	*- FL
19	1		*FRONT DOOR HANDLE RH	Cut	214.95 FL	*214.95 FL
20	1		*FRONT DOOR WEATHERSTRIP RH	Serviceable	88.79 FL	*- FL
21	1		*FRONT DOOR UPPER HINGE RH	Repair	74.77 FL	*- FL
22	1		*FRONT DOOR LOWER HINGE RH	Repair	74.77 FL	*- FL
23	1		*FRONT DOOR CHECKER RH	Serviceable	65.42 FL	*- FL
24	1		*REAR DOOR RH	Repair	953.27 FL	*- FL
25	1		*REAR DOOR WEATHERSTRIP RH	Serviceable	88.79 FL	*- FL
26	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
27	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	50.00 FS	*50.00 FS
28	1		*FRONT TYRE RH (90%)	Punctured	350.00 FS	*315.00 FS
29	1		*FRONT DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	50.00 FS	*- FS
30	1		*REAR DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,985.74</b>	<b>4,888.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	742.57	446.31
<b>Total Parts (\$\$)</b>	<b>7,243.17</b>	<b>4,441.79</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST ACCIDENT AREAS & ETC	New	1,000.00	600.00
2	LABOUR CHARGE FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH ,REAR DOOR RH & ETC	New	1,000.00	880.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF FRONT DOOR RH	New	150.00	0.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISMS & ETC.TO EFFECT REPLACE OF REAR DOOR RH	New	150.00	0.00
5	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH ,FRONT LOWER ARM RH ,FRONT UPPER ARM RH ,FRONT KNUCKLE ARM RH ,FRONT WHEEL BEARING HUB RH & ETC	New	350.00	200.00
6	TO WHEEL ALIGNMENT & BALANCING	New	90.00	80.00
7	LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC	New	120.00	60.00
8	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	120.00
9	TO CHECK WIRING & ELECTRICAL SYSTEM	New	120.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>3,130.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**